



Report

US \$49.99

2015 Mercedes-Benz Sprinter 3500

308 mi | VIN: WDAPF4CC0F9612796

chassis and Cab | 3.0L V6 F DOHC 24V | Diesel | Rear wheel drive



NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX



1 Service History Record



At Least 1 Open Recall



CARFAX 1-Owner Vehicle



Personal Vehicle



Last Owned in Iowa

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/18/26 at 7:17:02 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported

Manufacturer Recall

At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.

Recall Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

 **Guaranteed**
No Problem

GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

**Ownership History**

The number of owners is estimated

 **Owner 1**

Year purchased

2015

Type of owner

Personal

Estimated length of ownership

10 yrs. 9 mo.

Owned in the following states/provinces

Iowa

Estimated miles driven per year

Last reported odometer reading

308

**Detailed History****Owner 1**

Purchased: 2015

Personal Vehicle

Date	Mileage	Source	Comments
01/19/2015	5	Loeber Motors, Inc. Lincolnwood, IL 847-675-1000 loebermotors.com ★ 4.5 / 5.0 197 Verified Reviews ♥ 154 Customer Favorites	 Vehicle serviced Pre-delivery inspection completed
09/23/2015	308	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Title or registration issued _ First owner reported _ Titled or registered as personal vehicle Vehicle color noted as Cream
04/11/2016		Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
03/28/2017		Mercedes-Benz USA LLC	Manufacturer Safety recall issued _ NHTSA #19V003 Recall #2017030012 Model 906. Model Years 2007-2017. Replace Drivers Side Airbag. Launched MY07-14: March 2 Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall  Learn more about this recall

Description: Certain Sprinter vehicles are equipped with driver side front airbags provided by the supplier TK Holdings Inc. ("Takata") and its successor Joyson Safety Systems ("JSS"). On January 2, 2019, JSS filed another Defect Information Report with NHTSA announcing a defect in the subject inflators. According to JSS/Takata, the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event of an airbag activation. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture.

According to JSS/Takata, activation of a nondesiccated PSAN inflator with degraded propellant may cause the inflator to rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Remedy: Daimler Vans USA LLC will conduct a recall to replace the driver-side front airbag modules in the potentially affected Daimler Vans vehicles.

04/07/2017

Iowa
Motor Vehicle Dept.
Dixon, IA
Title #82AG13042

Registration issued or renewed

Vehicle color noted as Cream

04/09/2018

Iowa
Motor Vehicle Dept.
Dixon, IA
Title #82AG13042

Registration issued or renewed

Vehicle color noted as Cream

11/15/2018

Mercedes-Benz USA LLC

Manufacturer Safety recall issued

NHTSA #19V004
Recall #2018110007 Model 906 (Sprinter), Model
Years 2012 - 2014 Mercedes-Benz and
Freightliner Replace Front Passenger-s
Status: Remedy Available

Click here or call 1-800-367-6372 to locate an
authorized Mercedes-Benz dealer near you to obtain
more information about this recall

➔ **Learn more about this recall**

Description: Certain Sprinter vehicles are equipped with passenger-side front airbags provided by the supplier TK Holdings Inc. ("Takata") and its successor Joyson Safety Systems ("JSS"). On January 2, 2019 JSS filed another Defect Information Report with NHTSA announcing a defect in the subject inflators. According to JSS/Takata, the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event of an airbag activation. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Daimler AG ("DAG") is not aware of any confirmed field incidents with the subject Takata SPI inflators. However, based on the information above and out of an abundance of caution, DAG will conduct a recall of the vehicles equipped with subject Takata SPI inflators in the United States as identified by JSS/Takata in the above-mentioned Defect Information Report. According to JSS/Takata, activation of a nondesiccated PSAN inflator with degraded propellant may cause the inflator to rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants. Daimler Vans USA LLC will conduct a recall to replace the passenger-side front airbag modules in the potentially affected Daimler Vans vehicles.

According to JSS/Takata, activation of a nondesiccated PSAN inflator with degraded propellant may cause the inflator to rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Remedy: Daimler Vans USA LLC will conduct a recall to replace the passenger-side front airbag modules in the potentially affected Daimler Vans vehicles.

04/09/2019

Iowa
Motor Vehicle Dept.
Dixon, IA
Title #82AG13042

Registration issued or renewed

Vehicle color noted as Cream

04/01/2020

Mercedes-Benz USA LLC

Manufacturer Service Campaign issued

Campaign #2020040004 SERVICE CAMPAIGN -
BLUETEC UPDATE

Click here or call 1-800-367-6372 to locate an
authorized Mercedes-Benz dealer near you to obtain
more information about this campaign

➔ **Learn more about this campaign**

Description: On 2021-03-09, Daimler AG ("DAG") and Mercedes-Benz USA, LLC ("MBUSA") reached a settlement with the United States Department of Justice ("DOJ"), the Environmental Protection Agency "EPA"), the California Air Resources Board ("CARB"), and the California Attorney General's Office ("CA AG") regarding the emissions control system in MY09 to MY16 OM642 and OM651 BlueTEC II diesel vehicles sold or leased in the US. As part of this settlement, MBUSA is offering Owners and Lessees of these subject vehicles a modification to the vehicle's emissions control system, referred to as an Emission Modification.

Remedy: Your authorized Mercedes-Benz dealer will install the emission modification that updates the emission control system software on your vehicle and involves an exchange of certain components based on your vehicle model and year. More information can be found at www.bluetecupdate.mbusa.com/www.bluetecupdate.mbvans.com/www.bluetecupdate.freightlinersprinterusa.com

04/08/2020	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
04/08/2021	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
08/06/2021	Mercedes-Benz USA LLC	Manufacturer Safety recall issued NHTSA #21V042 Recall #2021070007 Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall  Learn more about this recall
Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain 5-ton Sprinter vehicles from platform 906 (NCV3) that were upfitted into campers or recreational vehicles ("RVs"), one or more of the rear-wheel speed sensors may experience an electrical failure, which potentially lead to a disablement of the ESP control unit functions. Other performance issues might also be detected. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash. An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the rear-wheel speed sensors against a variant with higher robustness against moisture intrusion. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash. Remedy: An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the rear-wheel speed sensors against a variant with higher robustness against moisture intrusion.		
04/12/2022	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
04/14/2023	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
04/15/2024	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
04/11/2025	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream
04/27/2026	Iowa Motor Vehicle Dept. Dixon, IA Title #82AG13042	Registration issued or renewed Vehicle color noted as Cream

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Service Campaign

Automobile manufacturers issue a service campaign to address product technical issues that may not be related to safety or emissions standards. These issues are typically customer satisfaction initiatives.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



[About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.

7/18/26 7:17:02 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2015 MERCEDES-BENZ SPRINTER vehicle (VIN: WDAPF4CC0F9612796), which is based on information supplied to CARFAX and available as of 7/18/26 at 8:17 AM (EDT).

Customer Signature

Date

Dealer Signature

Date