




History-Based Value Report

History events affecting this vehicle's value



Vehicle History Report™

US \$44.99

2005 NISSAN TITAN XE

VIN: 1N6AA06B95N556096
 CLUB CAB PICKUP
 5.6L V8 F DOHC 32V
 GASOLINE
 REAR WHEEL DRIVE W/ 4X4

No accidents or damage reported to CARFAX

7 Service history records



At least 1 open recall



CARFAX 1-Owner vehicle


Personal vehicle

140,500 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/8/23 at 9:05:12 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History The number of owners is estimated		Owner 1
Year purchased		2005
Type of owner		Personal
Estimated length of ownership		18 yrs. 4 mo.
Owned in the following states/provinces		See Details
Estimated miles driven per year		12,861/yr
Last reported odometer reading		140,500

 Title History CARFAX guarantees the information in this section		Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon		<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits		<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

 Additional History Not all accidents / issues are reported to CARFAX		Owner 1
Total Loss No total loss reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.		<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported

Manufacturer Recall	At least 1 manufacturer recall requires service. Locate an authorized Nissan dealer near you to schedule an appointment.	Recall Reported
Basic Warranty	Original warranty estimated to have expired.	Warranty Expired



Detailed History







Owner 1
Purchased: 2005










Low mileage! This owner drove less than the industry average of 15,000 miles per year.


Personal Vehicle
12,861 mi/yr

Date	Mileage	Source	Comments
04/28/2005		NICB	Vehicle manufactured and shipped to original dealer
07/07/2005		Jerry Rome Nissan West Springfield, MA 413-746-2266 jerryromenissan.com ★ 5.0 / 5.0 6 Verified Reviews	 Vehicle serviced Pre-delivery inspection completed
08/07/2005	13	Massachusetts Motor Vehicle Dept.	Vehicle purchase reported Titled or registered as personal vehicle
08/09/2005		Massachusetts Motor Vehicle Dept. Chicopee, MA	Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Green
08/12/2005		Jerry Rome Nissan West Springfield, MA 413-746-2266 jerryromenissan.com ★ 5.0 / 5.0 6 Verified Reviews	 Vehicle serviced Vehicle washed/detailed
08/12/2005	72	Massachusetts Inspection Station West Springfield, MA	Passed safety inspection
08/26/2005		Massachusetts Motor Vehicle Dept. Chicopee, MA	Title issued or updated First owner reported Vehicle color noted as Green

05/16/2006	Jerry Rome Nissan West Springfield, MA 413-746-2266 jerryromenissan.com ★ 5.0 / 5.0 6 Verified Reviews	 Vehicle serviced Front brake pads replaced Rear brake pads replaced
08/17/2006 11,792	Massachusetts Inspection Station Springfield, MA	Passed safety inspection
12/13/2006	Nissan North America Inc.	Manufacturer Safety recall issued NHTSA #06V-459 Recall #R0616 TITAN KC DOOR HARN NTB07-009 Status: Remedy Available Locate an authorized Nissan dealer near you to obtain more information about this recall ⊖ Learn more about this recall
<div style="border: 1px solid blue; padding: 10px;"> <p>Description: THE WIRES IN THE HARNESS WERE ROUTED THROUGH THE REAR DOORS AND INTO THE BODY. THESE WIRES MAY BREAK DUE TO OVER BENDING OF THE HARNESS AS THE DOOR IS OPENED AND CLOSED. THE HARNESS CONTAINS WIRES FOR THE DRIVER SEAT BELT PRETENSIONER AND FOR THE FRONT PASSENGER SEAT BELT WHICH IS PART OF THE OCCUPANT CLASSIFICATION SYSTEM. WIRES FOR THE REAR AUDIO SPEAKERS ARE ALSO CONTAINED N THE HARNESS.</p> <p>IF THE WIRES FOR THE SEAT BELTS AND SPEAKER WIRES BREAK AND MAKE CONTACT, THERE IS A POSSIBILITY THAT THE PRETENSIONER MAY DEPLOY. IF THIS HAPPENS WHEN THE SEAT BELT IS RETRACTED, IT WILL NOT BE POSSIBLE TO USE THE SEAT BELT. IF ONE OF THE WIRES ON THE RIGHT SIDE HARNESS FOR THE SEAT BELT TENSION SENSOR BREAKS, THE PASSENGER SIDE FRONT AIR BAG WILL NOT DEPLOY AS DESIGNED IN A FRONTAL COLLISION INCREASING THE RISK OF A CRASH AND PERSONAL INJURY.</p> <p>Remedy: DEALERS WILL REPLACE THE WIRE HARNESS COVER WITH A DIFFERENT TYPE THAT PREVENTS OVER BENDING OF THE HARNESS AND THE HARNESS WILL BE REROUTED.</p> </div>		
05/15/2007 28,225	Jerry Rome Nissan West Springfield, MA 413-746-2266 jerryromenissan.com ★ 5.0 / 5.0 6 Verified Reviews	 Vehicle serviced Oil and filter changed Rear ABS sensor assembly replaced ABS sensor replaced
06/01/2007	Massachusetts Motor Vehicle Dept. Chicopee, MA	Registration issued or renewed Vehicle color noted as Green

08/03/2007	33,468	Massachusetts Inspection Station Chicopee, MA	Passed safety inspection
08/03/2008		Nissan North America Inc.	<p>Manufacturer Safety recall issued NHTSA #08V-284 Recall #PB077 ARM/TTN COND FAN NTB08-068 Status: Remedy Available</p> <p>Locate an authorized Nissan dealer near you to obtain more information about this recall</p> <p> Learn more about this recall</p>
<div style="border: 1px solid #007bff; padding: 10px;"> <p>Description: THE FAN MOTOR MAY NOT BE PROPERLY SEALED ALLOWING EXCESSIVE WATER INTRUSION AND INADEQUATE DRAINAGE OF MOISTURE. THIS COULD CAUSE CORROSION IN THE MOTOR LEADING POSSIBLY TO OVERHEATING AND A FIRE.</p> <p>Remedy: DEALERS WILL INSTALL A 'THERMAL PROTECTOR KIT' AND TEST THE AIR CONDITIONING CONDENSER FAN MOTOR AND REPLACE IT IF NECESSARY.</p> </div>			
10/16/2008	57,228	California Motor Vehicle Dept. Placerville, CA	Odometer reading reported
10/24/2008	57,250	California Inspection Station	Passed emissions inspection
10/24/2008		California Motor Vehicle Dept. Placerville, CA	<p>Title issued or updated Loan or lien reported Registration updated when owner moved the vehicle to a new location</p>
10/19/2009		California Motor Vehicle Dept. Redding, CA	Registration updated when owner moved the vehicle to a new location
01/25/2010		Service Facility	<p> Vehicle reconditioned</p>

12/02/2010	Nissan North America Inc.	<p>Manufacturer Safety recall issued NHTSA #10V-517 Recall #PC068 NISSAN ECM RELAY NTB10-137 Status: Remedy Available</p> <p>Locate an authorized Nissan dealer near you to obtain more information about this recall</p> <p> Learn more about this recall</p>
<p>Description: THE INTELLIGENT POWER DISTRIBUTION MODULE (IPDM) ASSEMBLY CONTAINS AN ENGINE CONTROL MODULE (ECM) RELAY THAT HAS A DIODE FOR ELECTRICAL CURRENT NOISE REDUCTION. THE ECM RELAY MAY ALLOW SILICON VAPOR TO FORM AND, OVER TIME, THE SILICON EVAPORATES FROM THE DIODE MOLDING WHICH CAUSES SILICON OXIDE TO DEVELOP ON THE ECM RELAY CONTACT DUE TO ARCING.</p> <p>THIS COULD CAUSE ENGINE STALLING INCREASING THE RISK OF A CRASH.</p> <p>Remedy: DEALERS WILL REPLACE THE ECM RELAY INSIDE THE IPDM ASSEMBLY.</p>		
02/09/2011	California Motor Vehicle Dept. Junction City, CA	<p>Registration updated when owner moved the vehicle to a new location</p>
03/01/2011 99,245	Chris's Engine Benicia, CA 707-746-5143 chrisengine.com/  1 Customer Favorite	 Vehicle serviced
11/07/2011	California Motor Vehicle Dept. Junction City, CA	<p>Registration updated when owner moved the vehicle to a new location</p>
10/03/2013	California Motor Vehicle Dept. Junction City, CA	<p>Title issued or updated Registration updated when owner moved the vehicle to a new location</p>
01/12/2015 125,230	Cornerstone Auto & Tire Center Weaverville, CA 530-623-3365  38 Customer Favorites	 Vehicle serviced
07/07/2016 140,500	South Dakota Motor Vehicle Dept. Rapid City, SD	<p>Title issued or updated Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Green</p>

02/12/2017	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Green
03/02/2018	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Green
02/15/2019	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Vehicle color noted as Green
02/09/2020	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Vehicle color noted as Green
02/07/2021	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Vehicle color noted as Green
02/07/2022	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Vehicle color noted as Green
02/05/2023	South Dakota Motor Vehicle Dept. Rapid City, SD	Registration issued or renewed Vehicle color noted as Green
02/09/2023	Nissan North America Inc.	<p>Manufacturer Safety recall issued NHTSA #23E-012 Recall #PC947 ARM TTN DR AB EM NTB23-080 Status: Remedy Available</p> <p>Locate an authorized Nissan dealer near you to obtain more information about this recall</p> <p> Learn more about this recall</p>

Description: THE RESIN EMBLEM ON THE DRIVER S AIRBAG MODULE COVER IN AFFECTED VEHICLES MAY HAVE REDUCED DURABILITY DUE TO POTENTIAL SUPPLIER PRODUCTION PROCESS VARIATION. IN THIS CONDITION, OVER TIME THE POSTS OF THE EMBLEM MAY DEVELOP CRACKS, AND THE EMBLEM AND RETAINER COMPONENTS COULD DETACH IN THE EVENT OF AN AIRBAG DEPLOYMENT.

A DETACHED EMBLEM AND/OR RETAINER COMPONENT MAY BECOME A PROJECTILE DURING AN AIRBAG DEPLOYMENT, INCREASING THE RISK OF INJURY TO VEHICLE OCCUPANTS.

Remedy: Dealers will inspect and, if necessary, replace the Driver Airbag Cover.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or

Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.

12/8/23 9:05:12 AM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2005 NISSAN TITAN vehicle (VIN: 1N6AA06B95N556096), which is based on information supplied to CARFAX and available as of 12/8/23 at 10:05 AM (EST).

Customer Signature

Date

Dealer Signature

Date