




History-Based Value Report

History events affecting this vehicle's value



Vehicle History Report™

US \$44.99

2010 TOYOTA COROLLA LE

VIN: JTDBU4EE4A9108160
 SEDAN 4 DR
 1.8L I4 F DOHC 16V
 GASOLINE
 FRONT WHEEL DRIVE

No accidents or damage reported to CARFAX

33 Service history records



At least 1 open recall



CARFAX 1-Owner vehicle


Personal vehicle

90,221 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/22/23 at 5:35:57 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History The number of owners is estimated		Owner 1
Year purchased		2010
Type of owner		Personal
Estimated length of ownership		13 years
Owned in the following states/provinces		North Carolina
Estimated miles driven per year		10,796/yr
Last reported odometer reading		90,221

 Title History CARFAX guarantees the information in this section		Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon		<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits		<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. View Terms View Certificate		

 Additional History Not all accidents / issues are reported to CARFAX		Owner 1
Total Loss No total loss reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.		<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported

<p>Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Toyota dealer near you to schedule an appointment. View Toyota disclosure</p>	<p>Recall Reported</p>
<p>Basic Warranty Original warranty estimated to have expired.</p>	<p>Warranty Expired</p>




Detailed History



Owner 1
Purchased: 2010

Personal Vehicle
10,796 mi/yr





Date	Mileage	Source	Comments
Not Reported		NICB	Vehicle manufactured and shipped to original dealer
09/30/2009		Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites	 Vehicle serviced Inspection completed Maintenance inspection completed Safety inspection performed Oil and filter changed Emissions inspection performed
01/27/2010		Toyota Motor Sales, USA, Inc.	Manufacturer Safety recall issued NHTSA #10V023 Recall #90L SAFETY RECALL 90L - POTENTIAL FLOOR MAT INTERFERENCE WITH ACCELERATOR PEDAL Status: Remedy Available Locate an authorized Toyota dealer near you to schedule an appointment ⊖ Learn more about this recall





Description: Toyota is recalling certain Model Year 2008-2010 Highlander, Model Year 2009-2010 Corolla, Venza and Matrix passenger vehicles. The accelerator pedal can get stuck in the wide open position due to its being trapped by an unsecured or incompatible driver's floor mat. This recall is an expansion of a campaign of 3.8 million other Toyota vehicles announced in 2009 for the same issue (see 09V-388).





A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death.






Remedy: Toyota will modify or replace the accelerator pedals on the subject vehicles. Floor surface modifications are also being considered and will be included for any model for which it is deemed appropriate. Initially, dealers will be instructed on how to reshape the accelerator pedal for the repair. As replacement parts with the same shape as the modified pedal become available, they will be made available to the dealers for the repair. Customers who have had the pedal reshape remedy completed will have the opportunity to receive a new pedal if they desire, after replacement pedals become available. In addition, Toyota will replace any Toyota all-weather floor mat in a subject vehicle with a newly designed mat, free of charge. For those customers who have the previous design all-weather floor mat but do not need or want the newly designed all-weather floor mat, Toyota will recover the previous design all-weather floor mat and reimburse its price. The safety recall began March 30, 2010. Owners may contact Toyota at 1-800-331-4331.

03/13/2010	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384		Vehicle serviced Maintenance inspection completed Drive belts checked Oil and filter changed Serpentine belt replaced Air filter replaced
	★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		
05/21/2010 1	Anderson Auto Group 919-787-0099 andersonautonet.com		Vehicle offered for sale
	★ 4.4 / 5.0 118 Verified Reviews		
06/04/2010 6	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com		Vehicle serviced Vehicle washed/detailed Safety inspection performed
	★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		
06/10/2010 10	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com		Vehicle sold
	★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		







06/28/2010		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776556101795382		Registration issued or renewed Title or registration issued First owner reported Titled or registered as personal vehicle Loan or lien reported Passed safety inspection
09/27/2010	4,536	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Inspection completed Maintenance inspection completed Safety inspection performed Emissions inspection performed
09/27/2010		North Carolina Inspection Station Holly Springs, NC		Passed emissions inspection
09/27/2010		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776556101795382		Registration issued or renewed Passed safety inspection
09/28/2010	4,601	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com ★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		Vehicle serviced 5,000 mile service performed
02/24/2011	9,168	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com ★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		Vehicle serviced 10,000 mile service performed
08/05/2011	13,643	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com ★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		Vehicle serviced 15,000 mile service performed





09/23/2011	15,757	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Inspection completed Maintenance inspection completed Safety inspection performed Emissions inspection performed
09/23/2011		North Carolina Inspection Station Holly Springs, NC		Passed emissions inspection
09/23/2011		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776556101795382		Registration issued or renewed Loan or lien reported
12/19/2011	18,079	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com ★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		Vehicle serviced Recommended maintenance performed
04/27/2012	22,770	Fred Anderson Toyota Raleigh, NC 919-787-0099 fredandersontoyota.com ★ 4.5 / 5.0 533 Verified Reviews ❤️ 89 Customer Favorites		Vehicle serviced 25,000 mile service performed Vehicle washed/detailed Tire(s) balanced Four wheel alignment performed Wiper(s) replaced Alignment performed
07/27/2012	27,263	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Cabin air filter replaced/cleaned
09/28/2012	28,890	North Carolina Inspection Station Holly Springs, NC		Passed emissions inspection
10/12/2012		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776556101795382		Registration issued or renewed Loan or lien reported

01/08/2013	31,952	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Wiper(s) replaced Air filter replaced
05/13/2013	36,143	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Fuel system cleaned/serviced Light bulb(s) replaced
07/29/2013		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909		Title issued or updated Loan or lien reported
08/07/2013		Toyota Motor Sales, USA, Inc.		Manufacturer Service Campaign issued Campaign #BST SPECIAL SERVICE CAMPAIGN (SSC) BST MULTIPLE MODEL AND MODEL YEARS SMART STOP TECHNOLOGY Status: Remedy Available Locate an authorized Toyota dealer near you to schedule an appointment  Learn more about this campaign
<div style="border: 1px solid #0070C0; padding: 10px;"> <p>Description: In our continuing effort to ensure the best in customer satisfaction, Toyota has converted Limited Service Campaign (LSC) BST into Special Service Campaign (SSC) BST with no expiration date.</p> <p>Remedy: Toyota will install Smart Stop Technology on the involved model and model year vehicles. This feature will cut engine power in case of simultaneous application of both the accelerator and brake pedals at certain speeds and in certain driving conditions.</p> </div>				
10/09/2013	41,310	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Inspection completed Maintenance inspection completed Safety inspection performed Emissions inspection performed


10/10/2013		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909		Registration issued or renewed Loan or lien reported
01/22/2014	45,192	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Cabin air filter replaced/cleaned
06/20/2014	49,743	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed
09/29/2014	53,001	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Safety inspection performed Emissions inspection performed
09/29/2014		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909		Registration issued or renewed Loan or lien reported
11/21/2014	54,300	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Serpentine belt replaced Oil and filter changed Air filter replaced Air filter checked Fuel system cleaned/serviced
05/08/2015	58,849	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Brake fluid flushed/changed Fluids checked Automatic transmission serviced Wiper(s) replaced Breather filter replaced Oil and filter changed Transmission fluid changed

05/22/2015	59,190	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384		Vehicle serviced Brake rotor(s) resurfaced Front brakes replaced Front brake pads replaced
		★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		
09/17/2015	Toyota Motor Sales, USA, Inc.		Manufacturer Safety recall issued NHTSA #15V689 Recall #COM SAFETY RECALL COM REMEDY NOTICE - MULTIPLE MODELS AND MODEL YEARS - POWER WINDOW MASTER SWITCH (PWMS) Status: Remedy Available	
		Locate an authorized Toyota dealer near you to schedule an appointment		
		⊖ Learn more about this recall		
<p>Description: The Power Window Master Switch in the involved vehicles may have been manufactured with insufficient lubricant grease.</p> <p>If sufficient grease is not applied, under certain conditions the switch may develop a short circuit that can cause the switch assembly to overheat and melt. A melting switch can produce smoke and potentially lead to a fire.</p> <p>Remedy: Toyota is currently preparing the remedy for this condition. Once remedy preparations are complete, Toyota will send an owner notification letter by first class mail to owners of vehicles covered by this Safety Recall. Additional details on the remedy will be provided in future communications.</p>				
09/28/2015	62,130	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384		Vehicle serviced Maintenance inspection completed Safety inspection performed Emissions inspection performed
		★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		
09/29/2015	North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909		Registration issued or renewed Loan or lien reported	
11/20/2015	63,346	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384		Vehicle serviced Maintenance inspection completed Oil and filter changed
		★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		


05/11/2016	67,810	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Antifreeze/coolant checked Antifreeze/coolant flushed/changed Cabin air filter checked
09/23/2016	70,777	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Safety inspection performed Emissions inspection performed
09/23/2016		North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909		Registration issued or renewed Loan or lien reported
11/18/2016	72,081	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Fuel system cleaned/serviced
06/16/2017	76,597	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Cabin air filter replaced/cleaned Oil and filter changed
06/18/2017	76,664	Pep Boys Fuquay Varina, NC 919-567-0662 pepboys.com ★ 4.3 / 5.0 51 Verified Reviews ❤️ 57 Customer Favorites		Vehicle serviced Maintenance inspection completed Tire(s) balanced Tire(s) mounted Tire pressure monitoring system serviced
09/23/2017	79,777	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Safety inspection performed Emissions inspection performed


09/23/2017	North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909	Registration issued or renewed Loan or lien reported
11/03/2017 81,172	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites	 Vehicle serviced Maintenance inspection completed Oil and filter changed Tire condition and pressure checked Tires rotated
01/09/2018	Toyota Motor Sales, USA, Inc.	Manufacturer Safety recall issued NHTSA #18V024 Recall #G0R SAFETY RECALL G0R - REMEDY NOTICE MULTIPLE MODELS AND MODEL YEARS TAKATA FRONT PASSENGER AIRBAG INFLATOR (ZONE B) Status: Remedy Available Locate an authorized Toyota dealer near you to schedule an appointment  Learn more about this recall
<p>Description: The subject vehicles are equipped with front passenger airbag inflators produced by Takata. The propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause the inflator to explode during airbag deployment.</p> <p>In the event of an inflator explosion, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.</p> <p>Remedy: The remedy will consist of the replacement of the airbag inflator or the airbag assembly, depending on the vehicle model. Call 1-888-779-2075 to schedule your repair today!</p>		
03/24/2018 85,622	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites	 Vehicle serviced Maintenance inspection completed Oil and filter changed Air filter replaced Air filter checked Fuel system cleaned/serviced
09/29/2018 89,426	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites	 Vehicle serviced Maintenance inspection completed Wiper(s) replaced Tires rotated Safety inspection performed Emissions inspection performed


09/29/2018	North Carolina Motor Vehicle Dept. Holly Springs, NC Title #776793132108909	Registration issued or renewed Loan or lien reported
------------	---	--



Avoid financial headaches. Make sure the loan has been paid off if you're buying from a private seller. [Learn More](#)

10/10/2018 89,646	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Serpentine belt replaced Antifreeze/coolant flushed/changed Fluids checked Air filter replaced Antifreeze/coolant checked Automatic transmission serviced Cooling system serviced Air filter checked Alternator replaced Battery replaced Transmission fluid changed Alternator checked
-------------------	---	---	---

11/03/2018 90,221	Fast Lube Plus # 5143 Holly Springs, NC 919-577-6384 ★ 4.8 / 5.0 85 Verified Reviews ❤️ 114 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed Spark plug(s) replaced
-------------------	---	--	---



Hmm, we haven't received any information on this car since November 2018. Before you buy, ask the seller for recent service or repair records.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles

manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Toyota Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013 . This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to <http://toyota.com/recall> or <http://lexus.com/recall>.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.
7/22/23 5:35:57 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 TOYOTA COROLLA vehicle (VIN: JTDBU4EE4A9108160), which is based on information supplied to CARFAX and available as of 7/22/23 at 6:35 AM (EDT).

Customer Signature

Date

Dealer Signature

Date