




# Report

US \$44.99

## 2014 GMC Savana LT 3500

10 mi | VIN: 1GKZ7YFG5E1119707 |


Van | 6.0L V8 F OHV 16V | Flex Fuel | Rear wheel drive




**NO ACCIDENTS REPORTED**

No Accidents or Damage Reported to CARFAX


**CARFAX VALUE \$10,130**

-  At Least 1 Open Recall


---

-  **1** CARFAX 1-Owner Vehicle


---

-  Commercial Vehicle

---

-  Last Owned in Michigan

---

-  **13** Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/18/26 at 12:31:10 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.








## History-Based Value Report

# \$10,130

CARFAX Retail Value

### History events affecting this vehicle's value

-   No Accidents Reported
-   1-Owner Vehicle
-   Open Recall



## Additional History

Not all accidents / issues are reported to CARFAX

 **Owner 1**

<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated

<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at recalls.gm.com.	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2013
Type of owner	Commercial
Estimated length of ownership	12 yrs. 7 mo.
Owned in the following states/provinces	Michigan
Estimated miles driven per year	---
Last reported odometer reading	10

<b>CARFAX Detailed History</b>			
<b>Owner 1</b> Purchased: 2013			Commercial Vehicle
Date	Mileage	Source	Comments
10/15/2013	10	Michigan Motor Vehicle Dept. Pontiac, MI Title #118B2880205	<b>Title or registration issued</b> - First owner reported - Titled or registered as commercial vehicle
03/17/2014		General Motors	<b>Manufacturer Non-Compliance recall issued</b> - NHTSA #14V117 - Transport Canada# 2014083 - Recall #N140082 PASSENGER SIDE INSTRUMENT PANEL PERFORMANCE (HD VEHICLES) - Status: Remedy Available  Locate an authorized General Motors dealer to obtain more information about this recall.  <b>Learn more about this recall</b>
<b>Description:</b> General Motors is recalling certain model year 2009-2014 Chevrolet Express and GMC Savana vans manufactured January 27, 2009, through March 7, 2014 with a gross vehicle weight rating of 10,000 pounds and less and equipped with front passenger air bags. In the affected vehicles, during a frontal impact below the air bag deployment threshold, if an unbelted front passenger's head hits the instrument panel above where the passenger air bag is located, the panel may not sufficiently absorb the impact. As such, these vehicles fail to meet the requirements of Federal Motor Vehicle Safety Standard number 201, "Occupant Protection in Interior Impact."			

In the event of a crash below the air bag deployment threshold, an unbelted front passenger seat occupant has an increased risk of injury.

**Remedy:** Dealers will modify the passenger instrument panel free of charge.

02/23/2015	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b>
01/13/2016	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
12/27/2016	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
01/11/2018	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
05/03/2018	General Motors	<b>Manufacturer Safety recall issued</b> - NHTSA #18V295 - Transport Canada# 2018234 - Recall #N172086770 DRIVER SIDE WINDOW SWITCH INOPERATIVE - Status: Remedy Available  Locate an authorized General Motors dealer to obtain more information about this recall.  <a href="#">Learn more about this recall</a>
<p><b>Description:</b> General Motors has decided that a defect which relates to motor vehicle safety exists in 2014 - 2017 Chevrolet Express and GMC Savana vehicles (built through 6/21/16 and 6/17/16 respectively) equipped with power windows. Under certain conditions, liquid can enter the power window switches in these vehicles and cause corrosion, leading to high electrical resistance. High electrical resistance can cause the switch to heat up, smoke or melt, increasing the risk of fire and injury. Occupants may notice that the power window is malfunctioning or inoperative. Smoke or an odor from smoke or melting may also come from the door panel.</p> <p>A short circuit in these switches can cause the switch to heat up, smoke or melt. Over time, under rare circumstances, the switch can catch fire while the vehicle is on or up to ten minutes after the vehicle is shut off before the driver exits the vehicle, increasing the risk of injury to the driver or passengers.</p> <p><b>Remedy:</b> Replace driver side door window switch.</p>		
02/07/2019	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
02/04/2020	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
02/18/2021	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
02/17/2022	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
01/19/2023	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle
01/31/2024	Michigan Motor Vehicle Dept. Pontiac, MI	<b>Registration issued or renewed</b> - Titled or registered as commercial vehicle

Hmm, we haven't received any information on this car since January 2024. Before you buy, ask the seller for recent service or repair records.



## Glossary

**Commercial**

Vehicle was registered for business purposes.

**First Owner**




When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Manufacturer Recall**

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.  
5/18/26 12:31:10 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 GMC SAVANA vehicle (VIN: 1GKZ7YFG5E1119707), which is based on information supplied to CARFAX and available as of 5/18/26 at 1:31 PM (EDT).

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date