




Report

US \$44.99

2016 Ford Explorer Police Interceptor Utility

111,863 mi | VIN: 1FM5K8AR5GGC91765 |

4 Door Wagon/Sport Utility | 3.7L V6 F DOHC 24V | Gasoline | Front wheel drive w/ 4X4



CARFAX VALUE \$7,710

11 Service history records

At least 1 open recall

CARFAX 1-Owner vehicle

Last owned in Michigan

22 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/6/26 at 2:49:12 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

12/16/2016

Accident reported: minor damage with another motor vehicle



History-Based Value Report


\$7,710

CARFAX Retail Value

History events affecting this vehicle's value

1-Owner Vehicle

Service History

↓  Open Recall

↓  Minor Damage

Additional History

Not all accidents / issues are reported to CARFAX

 Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

Accident reported: 12/16/2016.

Minor Damage

Manufacturer Recall

At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.

Recall Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired

Title History

CARFAX guarantees the information in this section

 Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed
No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

Ownership History

The number of owners is estimated

 Owner 1

Year purchased

2016

Type of owner

Estimated length of ownership

9 yrs. 11 mo.

Owned in the following states/provinces

Michigan

Estimated miles driven per year

19,323/yr

Last reported odometer reading

111,863



Detailed History



Owner 1

Purchased: 2016

19,323 mi/yr

Date

Mileage

Source


Comments






04/08/2016

Ford Motor Company

Vehicle manufactured and shipped to original dealer

Original Window Sticker



<p>04/13/2016</p>	<p>3</p>	<p>Gorno Ford Woodhaven, MI 734-676-0031 gornoford.com</p> <p>★ 4.6 / 5.0 805 Verified Reviews ♥ 6,533 Customer Favorites</p>	<p>Vehicle offered for sale</p>
<p>04/18/2016</p>	<p>10</p>	<p>Gorno Ford Woodhaven, MI 734-676-0031 gornoford.com</p> <p>★ 4.6 / 5.0 805 Verified Reviews ♥ 6,533 Customer Favorites</p>	<p> Vehicle serviced - Pre-delivery inspection completed</p>
<p>04/27/2016</p>	<p>75</p>	<p>Michigan Motor Vehicle Dept. Garden City, MI Title #110E1170423</p>	<p>Title issued or updated - Registration issued or renewed - First owner reported</p>
<p>12/16/2016</p>	<p>Damage Report</p>	<p>Damage Report</p>	<p>Accident reported: minor damage with another motor vehicle - Damage to right rear</p> <div data-bbox="852 934 1258 1092"> <p>Damage Severity Scale</p>  <p>Minor Moderate Severe</p> </div> <div data-bbox="852 1102 1258 1554"> <p>Damage Location</p>  </div> <div data-bbox="876 1585 1502 1669"> <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p> </div>
<p>03/25/2017</p>	<p>12,714</p>	<p>North Brothers Ford Westland, MI 734-421-1300 northbros.com</p> <p>★ 4.4 / 5.0 236 Verified Reviews ♥ 4 Customer Favorites</p>	<p> Vehicle serviced - Maintenance inspection completed - Battery/charging system checked</p>
<p>05/11/2017</p>		<p>North Brothers Ford Westland, MI 734-421-1300 northbros.com</p>	<p> Vehicle serviced</p>

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

05/31/2017

North Brothers Ford
Westland, MI
734-421-1300
northbros.com



Vehicle serviced
- Trim checked

★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

02/23/2018

North Brothers Ford
Westland, MI
734-421-1300
northbros.com



Vehicle serviced
- Alignment checked
- Rear suspension serviced

★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

02/11/2019

65,504

North Brothers Ford
Westland, MI
734-421-1300
northbros.com



Vehicle serviced
- Maintenance inspection completed
- Engine/powertrain computer/module checked

★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

02/25/2019

66,090

Midas
Westland, MI
734-729-4430
midas.com



Vehicle serviced
- Alignment performed
- Four wheel alignment performed
- Two wheel alignment performed

★ 4.8 / 5.0 78 Verified Reviews
♥ 45 Customer Favorites

03/06/2019

66,528

North Brothers Ford
Westland, MI
734-421-1300
northbros.com



Vehicle serviced
- Maintenance inspection completed

★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

12/17/2020

97,443

North Brothers Ford
Westland, MI
734-421-1300
northbros.com



Vehicle serviced
- Maintenance inspection completed

★ 4.4 / 5.0 236 Verified Reviews
♥ 4 Customer Favorites

08/18/2021

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #21V537
- Recall #21S32 REAR TOE LINK REPLACEMENT
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

🔍 [Learn more about this recall](#)

Description: VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS COULD EXPERIENCE A SEIZED REAR SUSPENSION TOE LINK BALL JOINT RESULTING IN A FRACTURED REAR SUSPENSION TOE LINK.

A REAR TOE LINK FRACTURE MAY CAUSE A LOSS OF STEERING CONTROL, INCREASING THE RISK OF A CRASH.



Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE BOTH REAR TOE LINKS AND ADJUST REAR TOE FREE OF CHARGE PARTS AND LABOR.

08/19/2021

Ford Motor Company

Manufacturer Customer Satisfaction Program issued
- Program #21B05 HIGH SPEED COOLING FAN MOTOR RELAY

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

01/05/2022	111,283	<p>Midas Westland, MI 734-729-4430 midas.com</p> <p>★ 4.8 / 5.0 78 Verified Reviews</p> <p>♥ 45 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Tire pressure sensor replaced - Tire(s) mounted
02/08/2022	111,863	<p>North Brothers Ford Westland, MI 734-421-1300 northbros.com</p> <p>★ 4.4 / 5.0 236 Verified Reviews</p> <p>♥ 4 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed
02/17/2022		Ford Motor Company		<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #20V675 - Recall #20S62 REAR TOE LINK BALL JOINT INSPECTION - Status: Remedy Available <p>Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information</p> <p>➤ Learn more about this recall</p>
<p>Description: OUR RECORDS INDICATE THAT A FORD SAFETY RECALL WAS PREVIOUSLY PERFORMED ON YOUR VEHICLE TO REPLACE THE REAR SUSPENSION TOE LINKS. ASSESSMENT OF FIELD DATA INDICATES THAT THE BALL JOINT USED TO ATTACH THE REAR TOE LINK MAY BE SUSCEPTIBLE TO SEIZING IN CERTAIN HIGH CORROSION AREAS. A SEIZED TOE LINK BALL JOINT CAN INCREASE BENDING STRESSES IN THE TOE LINK AND POTENTIALLY LEAD TO A FRACTURE.</p> <p>REAR TOE LINK FRACTURE WHILE DRIVING COULD RESULT IN UNUSUAL VEHICLE HANDLING CHARACTERISTICS, OR DIFFICULTY CONTROLLING THE VEHICLE AND MAY INCREASE THE RISK OF A CRASH.</p> <p>Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH REAR TOE LINK BALL JOINTS AND, IF NECESSARY, REPLACE THE REAR WHEEL KNUCKLE(S), AND ADJUST REAR TOE FREE OF CHARGE (PARTS AND LABOR).</p>				
08/31/2022		Ford Motor Company		<p>Manufacturer Customer Satisfaction issued</p> <ul style="list-style-type: none"> - Program #21N01 HIGH SPEED COOLING FAN MOTOR RELAY <p>Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information</p>
01/23/2024		Ford Motor Company		<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #24V031 - Recall #24S02 EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION - Status: Remedy Not Yet Available <p>Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information</p> <p>➤ Learn more about this recall</p>
<p>Description: IN SOME OF THE AFFECTED VEHICLES, IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.</p> <p>AN EXTERIOR A-PILLAR TRIM PART THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH.</p> <p>Remedy: FORD MOTOR COMPANY IS WORKING CLOSELY WITH ITS SUPPLIERS TO PRODUCE PARTS FOR THIS REPAIR. WHEN PARTS BECOME AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE PARTS AND LABOR. PARTS ARE ANTICIPATED TO BE AVAILABLE TOWARD THE LATTER HALF OF 2024.</p>				
05/27/2025		Ford Motor Company		<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #25V347 - Recall #25S53 EXTERIOR B-PILLAR APPLIQUE MOLDING INSPECTION - Status: Remedy Not Yet Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Learn more about this recall

Description: ON YOUR VEHICLE, THE DRIVER AND FRONT PASSENGER DOOR B-PILLAR TRIM APPLIQUES MAY BECOME PARTIALLY OR FULLY DETACHED. YOU MAY VISUALLY NOTICE THE B-PILLAR TRIM APPLIQUES SEPARATING FROM THE TOP OF THE FRONT DOORS WHEN ENTERING EXITING THE VEHICLE AND OR HEAR WIND NOISE AND RATTLING NOISE AS YOU DRIVE.

THIS MAY RESULT IN THE B-PILLAR TRIM APPLIQUES DETACHING WHILE DRIVING. A B-PILLAR TRIM APPLIQUE THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER VEHICLES, INCREASING THE RISK OF A CRASH.

Remedy: FORD MOTOR COMPANY IS WORKING TO PROVIDE PARTS FOR THIS REPAIR. WHEN THE REMEDY BECOMES AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE.

04/02/2026

Ford Motor Company

Manufacturer Customer Satisfaction issued
- Program #25N17 REAR VIEW CAMERA REPLACEMENT IF REQUIRED AFTER DEALER EVALUATION

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/6/26 at 2:49:12 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford or Lincoln Mercury Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Service Campaign

Automobile manufacturers issue a service campaign to address product technical issues that may not be related to safety or emissions standards. These issues are typically customer satisfaction initiatives.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
4/6/26 2:49:12 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2016 FORD EXPLORER vehicle (VIN: 1FM5K8AR5GGC91765), which is based on information supplied to CARFAX and available as of 4/6/26 at 3:49 PM (EDT).

Customer Signature

Date

Dealer Signature

Date