




Report

US \$44.99

2021 Ford Explorer Hybrid Police Interceptor Utility

10 mi | VIN: 1FM5K8AW7MNA07081 |


4 Door Wagon/Sport Utility | 3.3L V6 F DOHC 24V | Hybrid | Rear wheel drive w/ 4X4





NO ACCIDENTS REPORTED


No Accidents or Damage Reported to CARFAX


CARFAX VALUE \$20,360

-  1 Service History Record

-  At Least 1 Open Recall

-  1 CARFAX 1-Owner Vehicle

-  Last Owned in Michigan

-  9 Detailed Records Available






This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/5/26 at 3:13:25 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



History-Based Value Report

\$20,360
CARFAX Retail Value

History events affecting this vehicle's value

-  No Accidents Reported
-   1-Owner Vehicle
-   Open Recall




Additional History

Not all accidents / issues are reported to CARFAX


 Owner 1




<p>Total Loss No total loss reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p><input checked="" type="checkbox"/> No Issues Indicated</p>

Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2021
Type of owner	---
Estimated length of ownership	5 yrs. 3 mo.
Owned in the following states/provinces	Michigan
Estimated miles driven per year	---
Last reported odometer reading	10



CARFAX Detailed History			
 Owner 1 Purchased: 2021			
Date	Mileage	Source	Comments
12/23/2020		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker 
12/23/2020	3	Lunghamer Auto Sales Owosso, MI 989-447-2908 sigautogroup.com ★ 4.7 / 5.0 344 Verified Reviews ♥ 4,591 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Recommended maintenance performed
01/12/2021		Michigan Motor Vehicle Dept.	Vehicle purchase reported - Registration issued or renewed
01/15/2021	10	Michigan Motor Vehicle Dept. Battle Creek, MI	Title issued or updated - First owner reported

10/09/2023

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #23V675
- Recall #23S55 REAR AXLE BOLT FRACTURES

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, A REAR AXLE BOLT MAY FRACTURE.

IF YOUR VEHICLE WAS PREVIOUSLY REPAIRED FOR THIS ISSUE UNDER RECALL 22S27 TO APPLY THE ELECTRONIC PARKING BRAKE WHEN THE VEHICLE IS SHIFTED TO PARK, A FURTHER REPAIR IS NEEDED TO PREVENT REAR AXLE BOLT FRACTURE. A FRACTURED REAR AXLE BOLT WILL ALLOW THE REAR AXLE HOUSING TO MOVE OUT OF POSITION, RESULTING IN SEVERE NOISE AND VIBRATION. IF THE REAR AXLE BOLT BREAKS, THE DRIVESHAFT OR HALF-SHAFTS MAY BECOME DISCONNECTED, RESULTING IN LOSS OF TRANSMISSION TORQUE TO THE REAR WHEELS. TRANSMISSION TORQUE IS NECESSARY TO HOLD THE VEHICLE IN PARK AND IS ALSO NEEDED FOR THE VEHICLE TO MOVE FORWARD OR BACKWARD. LOSS OF THE VEHICLES FORWARD POWER INCREASES THE RISK OF CRASH AND INJURY. THE LOSS OF THE PRIMARY PARK TORQUE WILL ALLOW THE VEHICLE TO ROLL IN PARK IF THE PARKING BRAKE IS NOT APPLIED, INCREASING THE RISK OF CRASH AND INJURY.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER FOR THE REPAIR OF THE REAR AXLE BOLTS FREE OF CHARGE PARTS AND LABOR.

08/12/2024

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #24V598
- Recall #24S52 ENGINE BLOCK BREACHES
POWERTRAIN CONTROL MODULE UPDATE
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, THE ENGINE COULD FAIL PREMATURELY. IN THE EVENT OF AN ENGINE FAILURE, SIGNIFICANT QUANTITIES OF ENGINE OIL AND/OR FUEL VAPOR MAY BE RELEASED INTO THE UNDER-HOOD ENVIRONMENT AND MAY MIGRATE TO AND/OR ACCUMULATE NEAR IGNITION SOURCES RESULTING IN POTENTIAL UNDER-HOOD FIRE, LOCALIZED MELTING OF COMPONENTS, OR SMOKE.

ENGINE OIL AND/OR FUEL VAPOR THAT ACCUMULATES NEAR A COMBUSTIBLE SOURCE MAY IGNITE, INCREASING THE RISK OF A FIRE.

Remedy: SOFTWARE IS NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO UPDATE THE POWERTRAIN CONTROL MODULE SOFTWARE FREE OF CHARGE.

12/11/2024

Ford Motor Company

Manufacturer Customer Satisfaction issued

- Program #24N10 ENGINE BLOCK BREACHES

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

03/04/2026

Ford Motor Company

Manufacturer Safety recall issued

- Recall #26S14 FRONT WIPER MOTOR REPAIR

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, THE FRONT WINDSHIELD WIPER MOTOR MAY BECOME INOPERATIVE OR MAY OPERATE INTERMITTENTLY.

THIS MAY RESULT IN REDUCED VISIBILITY OR LOSS OF VISIBILITY IN CERTAIN CONDITIONS, INCREASING THE RISK OF A CRASH.

03/31/2026

Ford Motor Company

Manufacturer Customer Satisfaction issued

- Program #25N17 REAR VIEW CAMERA
REPLACEMENT IF REQUIRED AFTER DEALER
EVALUATION

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford or Lincoln Mercury Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
5/5/26 3:13:25 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2021 FORD EXPLORER HYBRID vehicle (VIN: 1FM5K8AW7MNA07081), which is based on information supplied to CARFAX and available as of 5/5/26 at 4:13 PM (EDT).

Customer Signature

Date

Dealer Signature

Date