




History-Based Value Report

History events affecting this vehicle's value



Vehicle History Report™

US \$44.99

**2016 FORD EXPLORER
POLICE INTERCEPTOR
UTILITY**

VIN: 1FM5K8AR7GGB07054
4 DOOR WAGON/SPORT
UTILITY
3.7L V6 F DOHC 24V
GASOLINE
FRONT WHEEL DRIVE W/ 4X4
Original Window Sticker

No accidents or damage reported to CARFAX

11 Service history records


At least 1 open recall



CARFAX 1-Owner vehicle


Last owned in Michigan

116,666 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/15/24 at 7:16:17 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2015
Type of owner	---
Estimated length of ownership	8 yrs. 8 mo.










Owned in the following states/provinces	Michigan
Estimated miles driven per year	21,430/yr
Last reported odometer reading	116,666






CARFAX Detailed History

Owner 1
Purchased: 2015

21,430 mi/yr

Date	Mileage	Source	Comments
10/01/2015		Ford Motor Company	<p>Vehicle manufactured and shipped to original dealer</p>  <p>Original Window Sticker</p>
10/05/2015	9	<p>Signature Ford of Perry Perry, MI 800-364-2868 sigautogroup.com</p> <p>★ 5.0 / 5.0 27 Verified Reviews</p>	<p> Vehicle serviced Pre-delivery inspection completed Maintenance inspection completed Battery/charging system checked Brakes checked Tire condition and pressure checked</p>
10/09/2015	10	<p>Michigan Motor Vehicle Dept. Battle Creek, MI Title #290D2810119</p>	<p>Title issued or updated First owner reported</p>
12/02/2016	21,043	<p>Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com</p> <p>★ 4.7 / 5.0 96 Verified Reviews ♥ 87 Customer Favorites</p>	<p> Vehicle serviced Throttle body replaced Drivability/performance checked Transfer case removed to complete repairs</p>

05/30/2017	38,392	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ♥ 87 Customer Favorites	 Vehicle serviced Steering/suspension checked
10/02/2017		Ford Motor Company	Manufacturer Customer Satisfaction Program issued Program #17M06 CANISTER PURGE VALVE LEAKS Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
10/18/2017	50,609	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ♥ 87 Customer Favorites	 Vehicle serviced Wing/spoiler installed
03/01/2018	54,862	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ♥ 87 Customer Favorites	 Vehicle serviced Alignment checked Rear suspension serviced
04/20/2018	59,186	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ♥ 87 Customer Favorites	 Vehicle serviced Rear driveshaft replaced Driveshaft replaced Tire condition and pressure checked

05/04/2018	59,215	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ❤️ 87 Customer Favorites		Vehicle serviced Transfer case removed to complete repairs
06/29/2018	64,999	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ❤️ 87 Customer Favorites		Vehicle serviced
08/17/2018	67,970	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ❤️ 87 Customer Favorites		Vehicle serviced Cooling system checked Engine oil/fluid leak checked Water pump replaced Water pump gasket replaced
07/16/2019	91,114	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ❤️ 87 Customer Favorites		Vehicle serviced PCM reprogrammed
03/18/2021	116,666	Lakeview Ford Lincoln Inc Battle Creek, MI 269-441-2500 shoplakeviewford.com ★ 4.7 / 5.0 96 Verified Reviews ❤️ 87 Customer Favorites		Vehicle serviced Tires rotated

08/18/2021

Ford Motor Company

Manufacturer Safety recall issued

NHTSA #21V537

Recall #21S32 REAR TOE LINK
REPLACEMENT

Status: Remedy Available

Locate an authorized Ford or Lincoln
dealer or call 866-436-7332 to obtain
more information **Learn more about this recall**

Description: VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS COULD EXPERIENCE A SEIZED REAR SUSPENSION TOE LINK BALL JOINT RESULTING IN A FRACTURED REAR SUSPENSION TOE LINK.

A REAR TOE LINK FRACTURE MAY CAUSE A LOSS OF STEERING CONTROL, INCREASING THE RISK OF A CRASH.

Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE BOTH REAR TOE LINKS AND ADJUST REAR TOE FREE OF CHARGE PARTS AND LABOR.

08/19/2021

Ford Motor Company

Manufacturer Customer Satisfaction Program issuedProgram #21B05 HIGH SPEED
COOLING FAN MOTOR RELAYLocate an authorized Ford or Lincoln
dealer or call 866-436-7332 to obtain
more information

02/17/2022

Ford Motor Company

Manufacturer Safety recall issued

NHTSA #20V675

Recall #20S62 REAR TOE LINK BALL
JOINT INSPECTION

Status: Remedy Available

Locate an authorized Ford or Lincoln
dealer or call 866-436-7332 to obtain
more information **Learn more about this recall**

Description: OUR RECORDS INDICATE THAT A FORD SAFETY RECALL WAS PREVIOUSLY PERFORMED ON YOUR VEHICLE TO REPLACE THE REAR SUSPENSION TOE LINKS. ASSESSMENT OF FIELD DATA INDICATES THAT THE BALL JOINT USED TO ATTACH THE REAR TOE LINK MAY BE SUSCEPTIBLE TO SEIZING IN CERTAIN HIGH CORROSION AREAS. A SEIZED TOE LINK BALL JOINT CAN INCREASE BENDING STRESSES IN THE TOE LINK AND POTENTIALLY LEAD TO A FRACTURE.

REAR TOE LINK FRACTURE WHILE DRIVING COULD RESULT IN UNUSUAL VEHICLE HANDLING CHARACTERISTICS, OR DIFFICULTY CONTROLLING THE VEHICLE AND MAY INCREASE THE RISK OF A CRASH.

Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH REAR TOE LINK BALL JOINTS AND, IF NECESSARY, REPLACE THE REAR WHEEL KNUCKLE(S), AND ADJUST REAR TOE FREE OF CHARGE (PARTS AND LABOR).

08/31/2022

Ford Motor Company

Manufacturer Customer Satisfaction Program issued

Program #21N01 HIGH SPEED COOLING FAN MOTOR RELAY

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

01/23/2024

Ford Motor Company

Manufacturer Safety recall issued

NHTSA #24V031
Recall #24S02 EXTERIOR A PILLAR APPLIQUE INSPECTION
Status: Remedy Not Yet Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

⊖ [Learn more about this recall](#)

Description: IN SOME OF THE AFFECTED VEHICLES IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

AN EXTERIOR A-PILLAR TRIM PART THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH.

Remedy: FORD MOTOR COMPANY IS WORKING CLOSELY WITH ITS SUPPLIERS TO PRODUCE PARTS FOR THIS REPAIR. WHEN PARTS BECOME AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE PARTS AND LABOR. PARTS ARE ANTICIPATED TO BE AVAILABLE TOWARD THE LATTER HALF OF 2024.

02/19/2024

Ford Motor Company

Manufacturer Customer Satisfaction Program issued

Program #23L06 OWNER GUIDE UPDATE

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

**Glossary****First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford or Lincoln Mercury Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:

[facebook.com/CARFAX](https://www.facebook.com/CARFAX)

@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
6/15/24 7:16:17 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2016 FORD EXPLORER vehicle (VIN: 1FM5K8AR7GGB07054), which is based on information supplied to CARFAX and available as of 6/15/24 at 8:16 AM (EDT).

Customer Signature	Date	Dealer Signature	Date
--------------------	------	------------------	------