

CARFAX

History-Based Value Report

\$5,450

CARFAX Retail Value

History events affecting this vehicle's value

- ↑

1

1-Owner Vehicle
- ↑

🔧

Service History
- ↑

🏠

Personal Vehicle
- ↓

🚗

Minor Damage

CARFAX

Vehicle History Report™

US \$44.99

2008 MAZDA MAZDA3

S SPORT

VIN: JM1BK344581855896

HATCHBACK 4 DR

2.3L I4 F DOHC 16V

GASOLINE

FRONT WHEEL DRIVE

🚗

Accident reported: minor damage

MINOR

MODERATE

SEVERE

🔧

49 Service history records

1

CARFAX 1-Owner vehicle

🏠

Personal vehicle

📊

107,342 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/17/25 at 12:07:04 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

08/26/2015

Accident reported: minor damage

Damage Severity Scale



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

Accident reported: 08/26/2015.

Minor Damage

Manufacturer Recall

No open recalls reported to CARFAX.



No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**
No Problem

GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.

[View Terms](#) | [View Certificate](#)

**Ownership History**

The number of owners is estimated

Owner 1

Year purchased

2008

Type of owner

Personal

Estimated length of ownership

17 yrs. 5 mo.

Owned in the following states/provinces

Massachusetts

Estimated miles driven per year

7,360/yr

Last reported odometer reading



107,342

**Detailed History****Owner 1**

Purchased: 2008





Personal Vehicle







7,360 mi/yr

Date	Mileage	Source	Comments
12/19/2007		NICB	Vehicle manufactured and shipped to Massachusetts
12/21/2007		Liberty Mazda Wakefield, MA 781-245-8000 liberty128mazda.com	 Vehicle serviced - Pre-delivery inspection completed
01/12/2008	15	Liberty Mazda Wakefield, MA 781-245-8000 liberty128mazda.com	Vehicle sold
01/12/2008		Massachusetts Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal vehicle
01/12/2008		Service Plan Co. Brighton, MA	Service contract issued
01/14/2008		Liberty Mazda Wakefield, MA	 Vehicle serviced - Maintenance inspection completed






781-245-8000
liberty128mazda.com







- Battery/charging system checked
- Brakes checked
- Emissions or safety inspection performed
- Tire condition and pressure checked
- Vehicle washed/detailed







01/15/2008		Massachusetts Motor Vehicle Dept. Brighton, MA		Registration issued or renewed - Vehicle color noted as Black
01/16/2008	16	Massachusetts Inspection Station Wakefield, MA		Passed safety inspection
02/01/2008		Massachusetts Motor Vehicle Dept. Brighton, MA Title #BF343236		Title issued or updated - First owner reported - Vehicle color noted as Black
04/16/2008	1,710	Liberty Mazda Wakefield, MA 781-245-8000 liberty128mazda.com		Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Battery/charging system checked - Brakes checked - Tire condition and pressure checked
07/25/2008	4,799	Liberty Mazda Wakefield, MA 781-245-8000 liberty128mazda.com		Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Battery/charging system checked - Brakes checked - Tire condition and pressure checked - Wipers/washers checked
10/11/2008	7,350	Liberty Mazda Wakefield, MA 781-245-8000 liberty128mazda.com		Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Battery/charging system checked - Brakes checked - Steering/suspension checked - Tire condition and pressure checked
01/16/2009	10,270	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
01/16/2009	10,271	Massachusetts Inspection Station Norwood, MA		Passed safety inspection - Passed emissions inspection






06/12/2009	15,053	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - 15,000 mile service performed - Battery/charging system checked - Brakes checked - Oil and filter changed - Tire condition and pressure checked - Transmission fluid flushed
08/14/2009	17,102	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Tire condition and pressure checked
09/04/2009	17,709	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Oil and filter changed - Tire condition and pressure checked
10/01/2009		Massachusetts Motor Vehicle Dept. Brighton, MA Title #BF343236		Registration issued or renewed - Vehicle color noted as Black
12/29/2009	21,796	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
12/29/2009	21,799	Massachusetts Inspection Station Norwood, MA		Passed safety inspection - Passed emissions inspection
04/02/2010	24,300	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Oil and filter changed - Tire condition and pressure checked
06/09/2010	27,513	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Battery/charging system checked - Brakes checked - Front brake rotor(s) resurfaced


- Noise checked
- Oil pan gasket replaced
- Thermostat housing/gasket replaced
- Tire condition and pressure checked
- Vibration checked

07/16/2010	29,308	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Four tires balanced - Four tires mounted - Tire condition and pressure checked
10/26/2010	32,868	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - 3,750 mile service performed - Battery/charging system checked - Brakes checked - Oil and filter changed - Tire condition and pressure checked
11/10/2010	33,123	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Battery/charging system checked - Brakes checked - One tire balanced - One tire mounted - Power steering pump replaced - Tire condition and pressure checked - Tire(s) balanced - Tire(s) mounted - Transmission fluid flushed - Wheel(s) repaired
12/29/2010	34,792	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - 3,750 mile service performed - Emissions or safety inspection performed
12/29/2010		Massachusetts Inspection Station Norwood, MA		Passed safety inspection <ul style="list-style-type: none"> - Passed emissions inspection
02/07/2011	35,717	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Engine checked - Engine/powertrain computer/module checked - Tire condition and pressure checked









04/29/2011	37,875	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - 3,750 mile service performed
07/30/2011	42,140	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Wiring repaired
09/03/2011	43,566	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Service contract claim - Suspension serviced - Maintenance inspection completed - Brakes checked - Shock absorber bushing(s) replaced - Tire condition and pressure checked
10/01/2011		Massachusetts Motor Vehicle Dept. Brighton, MA Title #BF343236	Registration issued or renewed - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Black
12/16/2011	47,621	Massachusetts Inspection Station Norwood, MA	Passed safety inspection - Passed emissions inspection
12/17/2011		Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Emissions or safety inspection performed
05/15/2012	52,943	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Brake rotor(s) replaced - Engine mount(s) replaced - Front brake pads replaced - Front brake rotor(s) replaced
08/14/2012	57,480	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed













09/27/2012	59,020	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Transmission fluid flushed
12/20/2012	62,420	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Emissions or safety inspection performed - Tires rotated
12/20/2012	62,422	Massachusetts Inspection Station Norwood, MA	Passed safety inspection - Passed emissions inspection
01/17/2013	63,970	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Drivability/performance checked - Tires rotated
05/03/2013		Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - 3,750 mile service performed - Brake fluid flushed/changed - Tires rotated
08/05/2013	70,848	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Service contract claim - Suspension serviced - Oil and filter changed
10/01/2013		Massachusetts Motor Vehicle Dept. West Roxbury, MA Title #BF343236	Registration issued or renewed - Vehicle color noted as Black
11/26/2013	74,592	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Fluids checked - Four wheel alignment performed - Oil and filter changed - Tires rotated

01/04/2014	75,473	Massachusetts Inspection Station West Roxbury, MA	Passed safety inspection - Passed emissions inspection
04/23/2014	78,629	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Four tires balanced - Four tires mounted - Four wheel alignment performed - Oil and filter changed
08/13/2014	82,492	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Fuel pump replaced - Oil and filter changed - Rear brake pads replaced
01/15/2015	84,451	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Brakes checked - Drive belts checked - Fluids checked - Emissions or safety inspection performed - Oil and filter changed - Tire condition and pressure checked
01/15/2015		Massachusetts Inspection Station Norwood, MA	Passed safety inspection - Passed emissions inspection
08/12/2015	88,202	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Oil and filter changed - Tires rotated
08/26/2015		Damage Report	 Accident reported: minor damage






Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

10/01/2015		Massachusetts Motor Vehicle Dept. West Roxbury, MA Title #BF343236		Registration issued or renewed - Vehicle color noted as Black
10/23/2015	88,804	Service Plan Co.		Service contract claim - Engine serviced
10/29/2015	88,807	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Battery replaced - Brake calipers cleaned/serviced - Front brake pads replaced - Front brake rotor(s) replaced
02/15/2016	90,111	Massachusetts Inspection Station West Roxbury, MA		Passed safety inspection - Passed emissions inspection
04/14/2016	90,630	Service Plan Co.		Service contract claim - Electrical system serviced
06/30/2016		Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Oil and filter changed - Seat or seat upholstery repaired
07/23/2016	92,087	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed
08/31/2016		Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com ★ 4.3 / 5.0 36 Verified Reviews		Vehicle serviced - Maintenance inspection completed - Four wheel alignment performed - Front shock absorber(s) replaced - Light bulb(s) replaced - Oil and filter changed - Oxygen sensor replaced - Radio replaced - Seat or seat upholstery repaired
11/21/2016	94,238	Service Plan Co.		Service contract claim - Suspension serviced
11/30/2016	94,242	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed

		 4.3 / 5.0 36 Verified Reviews	 <ul style="list-style-type: none"> - Lower control arm(s) replaced - Oil and filter changed
04/06/2017	96,764	Massachusetts Inspection Station West Roxbury, MA	Passed safety inspection <ul style="list-style-type: none"> - Passed emissions inspection
06/20/2017	97,425	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com  4.3 / 5.0 36 Verified Reviews	 Vehicle serviced <ul style="list-style-type: none"> - Service contract claim - Electrical system serviced - Maintenance inspection completed - Brake calipers cleaned/serviced - Door lock(s) replaced/repared - Front brake pads replaced - Front brake rotor(s) replaced - Oil and filter changed - Tires rotated
12/02/2017	98,773	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com  4.3 / 5.0 36 Verified Reviews	 Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Transmission computer/module checked - Transmission computer/module replaced
03/08/2018		Massachusetts Motor Vehicle Dept. West Roxbury, MA Title #BF343236	Registration issued or renewed <ul style="list-style-type: none"> - Vehicle color noted as Black
03/09/2018	99,595	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com  4.3 / 5.0 36 Verified Reviews	 Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Emissions or safety inspection performed - Oil and filter changed
03/09/2018		Massachusetts Inspection Station Norwood, MA	Passed safety inspection <ul style="list-style-type: none"> - Passed emissions inspection
08/28/2018	100,894	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com  4.3 / 5.0 36 Verified Reviews	 Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed
01/15/2019	102,081	Mazda Gallery Norwood, MA 781-769-9600 gallerygroup.com  4.3 / 5.0	 Vehicle serviced <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed - Tires rotated

36 Verified Reviews

07/02/2019		Ira Mazda Westwood, MA 781-769-9600 iramazda.com/ ★ 4.6 / 5.0 125 Verified Reviews ❤️ 9 Customer Favorites	 Vehicle serviced - Emissions or safety inspection performed - Oil and filter changed
07/02/2019	103,512	Massachusetts Inspection Station Norwood, MA	Passed safety inspection - Passed emissions inspection
10/02/2019		Massachusetts Motor Vehicle Dept. Medfield, MA Title #BF343236	Registration issued or renewed - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Black
10/21/2020	107,061	Ira Mazda Westwood, MA 781-769-9600 iramazda.com/ ★ 4.6 / 5.0 125 Verified Reviews ❤️ 9 Customer Favorites	 Vehicle serviced - Battery replaced
05/28/2021	107,112	Massachusetts Inspection Station Norwood, MA	Passed safety inspection - Failed emissions inspection
05/29/2021	107,114	Ira Mazda Westwood, MA 781-769-9600 iramazda.com/ ★ 4.6 / 5.0 125 Verified Reviews ❤️ 9 Customer Favorites	 Vehicle serviced - Antifreeze/coolant flushed/changed - Cabin air filter replaced/cleaned - Emissions or safety inspection performed - Spark plug(s) replaced
09/30/2021	107,164	Massachusetts Inspection Station Medfield, MA	Passed safety inspection - Passed emissions inspection
10/01/2021		Massachusetts Motor Vehicle Dept. Medfield, MA Title #BF343236	Registration issued or renewed - Vehicle color noted as Black
08/09/2022	107,342	Massachusetts Inspection Station Medfield, MA	Passed safety inspection - Passed emissions inspection



Hmm, we haven't received any information on this car since August 2022. Before you buy, ask the seller for recent service or repair records.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/17/25 at 12:07:04 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.
6/17/25 12:07:04 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2008 MAZDA MAZDA3 vehicle (VIN: JM1BK344581855896), which is based on information supplied to CARFAX and available as of 6/17/25 at 1:07 PM (EDT).

Customer Signature

Date

Dealer Signature

Date