
## **CARFAX** History-Based Value Report



	Vehicle History Report <sup>™</sup>	US \$44.99
2010 MAZDA MAZDA3 S SPORT VIN: JM1BL1S57A1185934 SEDAN 4 DR 2.5L I4 F DOHC 16V	Damage reported: minor damage     MINOR MODERATE SEVERE	
GASOLINE FRONT WHEEL DRIVE	24 Service history records	
	CARFAX 1-Owner vehicle	
	Personal vehicle	
	이라 129,889 Last reported odometer reading	

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/20/24 at 5:36:29 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<b>CARFAX</b> Accidents / issues are r	ent / Damag reported to CAF			
		Event 1		
07/17/2019 Damage reported: minor damage		Damage Severity Scal	e	
	MINOR	MODERATE	SEVERE	

<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage Damage reported: 07/17/2019.	Minor Damage
Manufacturer Recall Check with an authorized Mazda dealer for any open recalls.	No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	Guaranteed No Problem

## **Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits





**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARF/		<b>tership History</b> timated		Owner 1
ar purchased				2009
pe of owner				Personal
timated lengt	h of ownersh	ip	CARFAX	14 yrs. 3 mo.
vned in the fo	llowing state:	s/provinces	<b>1</b> 0WNER	Missouri
timated miles	s driven per ye	ear		10,613/yr
st reported or	dometer read	ing		129,889
Date	Mileage	Source	Comments	J
Date	Mileage	Source	Comments	)
08/13/2009	)	NICB	Vehicle manuf Missouri	actured and shipped to
08/27/2009	) 6	Bommarito Mazda Chevrolet Saint Louis, MO 314-487-9800 bommarito.com	Pre-delivery in	ed nspection completed

11/23/2009	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m <b>4.7 / 5.0</b> 422 Verified Reviews <b>8,961</b> Customer Favorites	×	Vehicle serviced
11/23/2009	Missouri Motor Vehicle Dept.		<b>Vehicle purchase reported</b> Titled or registered as personal vehicle
11/23/2009 25	Service Plan Co. Chesterfield, MO		Service contract issued
11/24/2009	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m <b>1.7 / 5.0</b> 422 Verified Reviews <b>8,961</b> Customer Favorites		Vehicle sold
12/30/2009	Missouri Motor Vehicle Dept. Chesterfield, MO Title #TAE77366		<b>Title issued or updated</b> Title or registration issued First owner reported Loan or lien reported
02/25/2010 4,7	<ul> <li>Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m</li> <li>★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites</li> </ul>	×	<b>Vehicle serviced</b> Maintenance inspection completed Battery/charging system checked Oil and filter changed Brakes checked Tire condition and pressure checked
02/25/2010 4,72	0 Bommarito Automotive ★ 4.5 / 5.0 407 Verified Reviews ♥ 7,723 Customer Favorites	×	<b>Vehicle serviced</b> Maintenance inspection completed Battery/charging system checked Brakes checked Tire condition and pressure checked

05/10/2010	9,630	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Tire condition and pressure checked Brakes checked Oil and filter changed Tires rotated
07/12/2010	12,382	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Maintenance inspection completed Steering/suspension checked
07/27/2010		Missouri Motor Vehicle Dept. Chesterfield, MO Title #TAE77366		<b>Title or registration issued</b> Loan or lien reported
08/03/2010	13,827	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	Vehicle serviced Maintenance inspection completed Brakes checked Tires rotated Battery/charging system checked Tire condition and pressure checked Oil and filter changed
11/11/2010	19,236	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Maintenance inspection completed 15,000 mile service performed Tire condition and pressure checked Battery/charging system checked Brakes checked

12/23/2010	21,812	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Maintenance inspection completed Glass checked
02/28/2011	24,552	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Maintenance inspection completed Battery/charging system checked Tire condition and pressure checked Brakes checked Oil and filter changed
05/27/2011	29,853	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Tire condition and pressure checked Battery/charging system checked Brakes checked Oil and filter changed Transmission fluid flushed
09/12/2011	34,382	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	Vehicle serviced Maintenance inspection completed Brakes checked Tire condition and pressure checked Electrical system checked Trim checked Oil and filter changed Battery/charging system checked
12/05/2011	38,571	Service Plan Co.	×	<b>Service contract claim</b> Tire(s) serviced
12/07/2011		Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	<b>Vehicle serviced</b> Steering/suspension checked

40,202	Bommarito Automotive Ellisville, MO	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked Tire condition and pressure checked Oil and filter changed
41,844	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	×	<b>Vehicle serviced</b> Maintenance inspection completed Emissions inspection performed
	Missouri Inspection Station Chesterfield, MO		Passed emissions inspection
	Missouri Motor Vehicle Dept. Chesterfield, MO Title #TAE77366		<b>Registration issued or renewed</b> Loan or lien reported
46,831	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Induction system serviced Brakes checked Tires rotated Tire condition and pressure checked Oil and filter changed Antifreeze/coolant flushed/changed
	Service Facility Clayton, MO	×	Vehicle serviced Windshield repaired
54,903	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritoautomotive.c om ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Tire condition and pressure checked Brakes checked Tires rotated Fluids checked Oil and filter changed
	41,844	Ellisville, MO★ 4.5 / 5.0407 Verified Reviews♥ 7,723 Customer¥1,844Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m41,844Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m41,844Bommarito Automotive Ellisville, MO 636-391-7200 hoomaritobuickgmc.co41,844Bommarito Automer Favorites41,844Missouri Inspection Station Chesterfield, MO41,844Missouri Motor Vehicle Dept. Chesterfield, MO Title #TAE7736646,831Bommarito Automotive Ellisville, MO 636-391-7200 bommaritobuickgmc.co m ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites54,903Bommarito Automotive Ellisville, MO 636-391-7200 bommarito Automotive.co om ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	Ellisville, MO $\bigstar$ 4.5 / 5.0407 Verified Reviews $\checkmark$ 7,723 Customer $\checkmark$ 7,723 Favorites41,844Bommarito AutomotiveEllisville, MO636-391-7200bommaritobuickgmc.com $\bigstar$ 4.7 / 5.0422 Verified Reviews $\heartsuit$ 8,961 Customer $\clubsuit$ 8,961 CustomerFavoritesMissouriInspection StationChesterfield, MOMissouriMotor Vehicle Dept.Chesterfield, MOTitle #TAE7736646,831Bommarito AutomotiveEllisville, MO636-391-7200bommaritobuickgmc.com $\bigstar$ 4.7 / 5.0422 Verified Reviews $\heartsuit$ 8,961 Customer $\clubsuit$ 4.7 / 5.04.22 Verified Reviews $\circlearrowright$ 4.7 / 5.04.22 Verified Reviews $\circlearrowright$ 8,961 Customer $\clubsuit$ 4.7 / 5.04.22 Verified Reviews $\circlearrowright$ 4.7 / 5.04.22 Verified Reviews $\circlearrowright$ 8,961 Customer $\clubsuit$ 9.61 Customer

10/25/2013	60,237	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritoautomotive.c om ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked Tires rotated Fluids checked Oil and filter changed Tire condition and pressure checked
02/26/2014	64,277	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritoautomotive.c om ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked Emission system checked Fluids checked Oil and filter changed Tire condition and pressure checked Emissions inspection performed
02/26/2014		Missouri Inspection Station Chesterfield, MO		Passed emissions inspection
03/04/2014		Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366		<b>Registration issued or renewed</b> Loan or lien reported Registration updated when owner moved the vehicle to a new location
07/14/2014	67,653	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritoautomotive.c om ★ 4.7 / 5.0 422 Verified Reviews ♥ 8,961 Customer Favorites	×	Vehicle serviced Maintenance inspection completed Four wheel alignment performed Alignment performed Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Battery/charging system checked Tire(s) balanced Tire(s) mounted
04/21/2015	75,146	Bommarito Automotive Ellisville, MO 636-391-7200 bommaritoautomotive.c om	×	Vehicle serviced Maintenance inspection completed Battery/charging system checked Tire condition and pressure checked Brakes checked Air filter replaced Fluids checked Oil and filter changed Engine checked Cabin air filter replaced/cleaned Transmission fluid flushed

	bommaritoautomotive.c om	Battery/charging system check Tire condition and pressure che Fluids checked Oil and filter changed Brakes checked Antifreeze/coolant flushed/cha	ecked
82,893	Missouri Inspection Station Saint Louis, MO	Passed emissions inspection	
	Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366	<b>Registration issued or renewed</b> Loan or lien reported	
	Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366	<b>Registration issued or renewed</b> Loan or lien reported	
	Damage Report	<b>Damage reported: minor damage</b> Damage to front	e
	0	Damage Severity Scale	
		MINOR MODERATE SEVERE	
ACCI	DENT & DAMAGE	<section-header><section-header><section-header></section-header></section-header></section-header>	
	CARI	<b>••</b> 8,961 Customer Favorites82,893Missouri Inspection Station Saint Louis, MOMissouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366Damage Report	Attifreeze/coolant flushed/chain ■ 8,961 Gustomer Favorites 82,893 Missouri Inspection Station Saint Louis, MO Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366 Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366 Damage Report Damage Report Damage reported: minor damage Damage to front Damage Severity Scale MINOR MODERATE SEVERE Damage Location FRONT LEFT LEFT CARFAX HAS THE MOST ACCIDENT & DAMAGE PERE

		CAP FOX	Minor damage is usually cosmetic, including dents or scratches to the vehicle body.
03/03/2020	112,739	Missouri Inspection Station Saint Louis, MO	Passed emissions inspection
03/11/2020		Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366	<b>Registration issued or renewed</b> Loan or lien reported
02/15/2022	129,889	Missouri Inspection Station Saint Louis, MO	Passed emissions inspection
02/16/2022		Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366	<b>Registration issued or renewed</b> Loan or lien reported
01/12/2024		Missouri Inspection Station	Passed emissions inspection
01/17/2024		Missouri Motor Vehicle Dept. Saint Louis, MO Title #TAE77366	<b>Registration issued or renewed</b> Loan or lien reported
		CAP FOX	Avoid financial headaches. Make sure the loan has been paid off if you're buying from a private seller. Learn More

Subscribers, please visit our Help Center at www.carfaxonline.com.

# **CARFAX** Glossary

## **Damage Indicator**

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

• This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/20/24 at 5:36:29 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

#### **First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

#### **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

#### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:

facebook.com/CARFAX

@CARFAXinc

Y

**C** About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 3/20/24 5:36:29 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 MAZDA MAZDA3 vehicle (VIN: JM1BL1S57A1185934), which is based on information supplied to CARFAX and available as of 3/20/24 at 6:36 PM (EDT).

**Customer Signature** 

Date

**Dealer Signature** 

Date