



Report

US \$44.99

2019 Ford Explorer Police Interceptor Utility

VIN: 1FM5K8AR7KGA16553

4 Door Wagon/Sport Utility | 3.7L V6 F DOHC 24V | Gasoline | Front wheel drive w/ 4X4



NO ACCIDENTS REPORTED

 No Accidents or Damage Reported to CARFAX

 42 Service History Records

 At Least 1 Open Recall

1

CARFAX 1-Owner Vehicle

 Last Owned in Michigan

 49 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/14/26 at 8:51:30 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	 Oil and filter changed	06/22/2026
 This car has been recently serviced. That's a good thing!		



Additional History

Not all accidents / issues are reported to CARFAX

 Owner 1

Total Loss

No total loss reported to CARFAX.

 No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

 No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

 No Issues Reported

Odometer Check

Mileage Inconsistency

Inconsistent mileage indicated.	
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem
GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

Ownership History The number of owners is estimated	Owner 1
Year purchased	2018
Type of owner	---
Estimated length of ownership	7 yrs. 8 mo.
Owned in the following states/provinces	Michigan
Estimated miles driven per year	---
Last reported odometer reading	---

Detailed History			
Owner 1 Purchased: 2018			
Date	Mileage	Source	Comments
10/08/2018		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker
10/08/2018		Zeigler Ford of Plainwell Plainwell, MI 269-685-5801 zeiglerfordplainwell.com ★ 4.5 / 5.0 203 Verified Reviews ♥ 1,929 Customer Favorites	Vehicle serviced - Pre-delivery inspection completed
10/09/2018		Dealer Inventory	Vehicle offered for sale
10/15/2018	14	Zeigler Ford of Plainwell Plainwell, MI 269-685-5801	Vehicle sold

zeiglerfordplainwell.com
★ 4.5 / 5.0 203 Verified Reviews
♥ 1,929 Customer Favorites

11/09/2018		Michigan Motor Vehicle Dept. Paw Paw, MI Title #201G3120202		Title issued or updated - Registration issued or renewed - First owner reported
03/01/2019	22	Zeigler Ford of Plainwell Plainwell, MI 269-685-5801 zeiglerfordplainwell.com ★ 4.5 / 5.0 203 Verified Reviews ♥ 1,929 Customer Favorites		Vehicle serviced - Electrical system checked
05/24/2019	9,393	Tapper XpressLube Paw Paw, MI 269-415-0119 tapperxpresslube.com ★ 4.8 / 5.0 211 Verified Reviews ♥ 109 Customer Favorites		Vehicle serviced - Oil and filter changed
07/24/2019	17,394	Tapper Ford, LLC. Paw Paw, MI 888-419-2643 tapperford.com ★ 4.8 / 5.0 371 Verified Reviews ♥ 2,143 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
09/25/2019		Tapper XpressLube Paw Paw, MI 269-415-0119 tapperxpresslube.com ★ 4.8 / 5.0 211 Verified Reviews ♥ 109 Customer Favorites		Vehicle serviced - Oil and filter changed
10/22/2019	24,650	Tapper Ford, LLC. Paw Paw, MI 888-419-2643 tapperford.com ★ 4.8 / 5.0 371 Verified Reviews ♥ 2,143 Customer Favorites		Vehicle serviced - Four tires balanced - Four tires mounted - Four tires replaced - Tire condition and pressure checked - Tire(s) replaced
12/26/2019	28,574	Tapper Ford, LLC. Paw Paw, MI 888-419-2643 tapperford.com ★ 4.8 / 5.0 371 Verified Reviews ♥ 2,143 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked
04/29/2020	37,030	Tapper XpressLube Paw Paw, MI 269-415-0119 tapperxpresslube.com ★ 4.8 / 5.0 211 Verified Reviews ♥ 109 Customer Favorites		Vehicle serviced - Oil and filter changed
06/16/2020	41,433	Tapper Ford, LLC. Paw Paw, MI 888-419-2643 tapperford.com ★ 4.8 / 5.0 371 Verified Reviews ♥ 2,143 Customer Favorites		Vehicle serviced - Brakes checked - Front brake pads replaced - Front brake rotor(s) replaced
06/22/2020	42,190	Tapper XpressLube Paw Paw, MI 269-415-0119		Vehicle serviced - Oil and filter changed

tapperxpresslube.com
★ 4.8 / 5.0 211 Verified Reviews
♥ 109 Customer Favorites

07/31/2020

45,542

Tapper XpressLube
Paw Paw, MI
269-415-0119
tapperxpresslube.com
★ 4.8 / 5.0 211 Verified Reviews
♥ 109 Customer Favorites



Vehicle serviced
- Oil and filter changed

09/22/2020

49,484

Tapper Ford, LLC.
Paw Paw, MI
888-419-2643
tapperford.com
★ 4.8 / 5.0 371 Verified Reviews
♥ 2,143 Customer Favorites



Vehicle serviced

04/15/2021

62,165

Tapper Ford, LLC.
Paw Paw, MI
888-419-2643
tapperford.com
★ 4.8 / 5.0 371 Verified Reviews
♥ 2,143 Customer Favorites



Vehicle serviced
- Maintenance inspection completed
- Air filter replaced
- Oil and filter changed
- Tires rotated

08/23/2021

70,316

Dan's Automotive of Bangor
Bangor, MI
269-427-1747
★ 5.0 / 5.0 50 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced
- Oil and filter changed
- Tire repaired

09/23/2021

Dan's Automotive of Bangor
Bangor, MI
269-427-1747
★ 5.0 / 5.0 50 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced
- Brake rotor(s) replaced
- Front brake pads replaced
- Front brake rotor(s) replaced
- Rear brake rotor(s) replaced

12/06/2021

76,437

Dan's Automotive of Bangor
Bangor, MI
269-427-1747
★ 5.0 / 5.0 50 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced
- Four tires replaced

04/18/2022

81,661

Tapper Ford, LLC.
Paw Paw, MI
888-419-2643
tapperford.com
★ 4.8 / 5.0 371 Verified Reviews
♥ 2,143 Customer Favorites



Vehicle serviced
- Maintenance inspection completed
- Oil and filter changed
- Serpentine belt replaced
- Starter replaced

09/28/2022

92,452

Tapper XpressLube
Paw Paw, MI
269-415-0119
tapperxpresslube.com
★ 4.8 / 5.0 211 Verified Reviews
♥ 109 Customer Favorites



Vehicle serviced
- Oil and filter changed

11/22/2022

95,957

Dan's Automotive of Bangor
Bangor, MI
269-427-1747
★ 5.0 / 5.0 50 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced
- Oil and filter changed

12/28/2022

98,142

Dan's Automotive of Bangor
Bangor, MI
269-427-1747



Vehicle serviced

		 5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		
01/19/2023	99,532	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Charcoal/vapor canister replaced - Evaporative emissions vent purge valve replaced
02/02/2023	100,902	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Ignition coil(s) replaced - Ignition system serviced - Spark plug(s) replaced
03/02/2023	103,417	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed
05/30/2023	111,486	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed
06/14/2023	112,996	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oxygen sensor replaced
07/18/2023	115,595	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Front wheel bearing(s)/hub(s) replaced - Wheel bearing(s)/hub(s) replaced
08/15/2023	118,589	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed
08/24/2023	118,973	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - A/C refrigerant recharged
10/10/2023	122,277	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
11/16/2023	125,146	Dan's Automotive of Bangor Bangor, MI 269-427-1747  5.0 / 5.0 50 Verified Reviews  7 Customer Favorites		Vehicle serviced - Brake pads replaced - Brake rotor(s) replaced - Four tires replaced - Rear brake pads replaced - Rear brake rotor(s) replaced
01/02/2024	128,471	Dan's Automotive of Bangor Bangor, MI 269-427-1747		Vehicle serviced - Oil and filter changed

★ 5.0 / 5.0 50 Verified Reviews

♥ 7 Customer Favorites

01/23/2024

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #24V031
- Recall #24S02 EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

➔ [Learn more about this recall](#)

Description: IN SOME OF THE AFFECTED VEHICLES, IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

AN EXTERIOR A-PILLAR TRIM PART THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH.

Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR. A TEMPORARY REPAIR MAY ALSO BE COMPLETED AS NEEDED.

03/06/2024

133,104

Tapper Ford, LLC.
Paw Paw, MI
888-419-2643
tapperford.com

★ 4.8 / 5.0 371 Verified Reviews

♥ 2,143 Customer Favorites



Vehicle serviced

- Alignment performed

03/08/2024

Ford Motor Company

Manufacturer Customer Satisfaction Program issued

- Program #22M06 CATALYTIC CONVERTER EXTENDED COVERAGE

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

03/12/2024

133,656

Dan's Automotive of Bangor
Bangor, MI
269-427-1747

★ 5.0 / 5.0 50 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed

04/22/2024

137,044

Dan's Automotive of Bangor
Bangor, MI
269-427-1747

★ 5.0 / 5.0 50 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Antifreeze/coolant checked
- Antifreeze/coolant flushed/changed
- Brake rotor(s) replaced
- Front brake pads replaced
- Front brake rotor(s) replaced
- Oil and filter changed
- Shift interlock cable/linkage replaced
- Timing chain replaced
- Timing chain tensioner/guide replaced
- Valve cover gasket(s) replaced
- Water pump gasket replaced
- Water pump replaced

07/01/2024

142,649

Dan's Automotive of Bangor
Bangor, MI
269-427-1747

★ 5.0 / 5.0 50 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Battery/charging system checked
- Battery replaced

07/17/2024

Dan's Automotive of Bangor
Bangor, MI
269-427-1747

★ 5.0 / 5.0 50 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed

07/31/2024	145,473	Dan's Automotive of Bangor Bangor, MI 269-427-1747 ★ 5.0 / 5.0 50 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - A/C refrigerant recharged - Cabin air filter replaced/cleaned
08/20/2024	147,060	Dan's Automotive of Bangor Bangor, MI 269-427-1747 ★ 5.0 / 5.0 50 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Tire repaired
08/29/2024	148,071	Dan's Automotive of Bangor Bangor, MI 269-427-1747 ★ 5.0 / 5.0 50 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Tire repaired
02/25/2025	151,131	Dan's Automotive of Bangor Bangor, MI 269-427-1747 ★ 5.0 / 5.0 50 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Oil and filter changed
03/30/2026	154,961	Tapper Ford Paw Paw, MI 888-419-2643 tapperford.com/ ★ 4.8 / 5.0 371 Verified Reviews ♥ 2,143 Customer Favorites		Vehicle serviced - Rear suspension checked
04/02/2026		Ford Motor Company		Manufacturer Customer Satisfaction issued - Program #25N17 REAR VIEW CAMERA REPLACEMENT IF REQUIRED AFTER DEALER EVALUATION Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
06/22/2026	7,575	Dan's Automotive of Bangor Bangor, MI 269-427-1747 ★ 5.0 / 5.0 50 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Oil and filter changed MILEAGE INCONSISTENCY
 The mileage reported here conflicts with this vehicle's odometer history. Ask a mechanic or the seller to confirm the actual mileage - this entry may just be a clerical error.				
Have Questions? Consumers, please visit our Help Center at www.carfax.com . Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com .				

CARFAX Glossary
First Owner When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership. Ford or Lincoln Mercury Recall The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer. Manufacturer Recall Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer. Mileage Inconsistency If an odometer reading is less than a previous reading but CARFAX is uncertain whether the discrepancy is a rollback or a clerical error, then CARFAX calls it a "Mileage Inconsistency". In this case, you should verify the mileage with your dealer or a qualified mechanic.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Service Campaign

Automobile manufacturers issue a service campaign to address product technical issues that may not be related to safety or emissions standards. These issues are typically customer satisfaction initiatives.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
7/14/26 8:51:30 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2019 FORD EXPLORER vehicle (VIN: 1FM5K8AR7KGA16553), which is based on information supplied to CARFAX and available as of 7/14/26 at 9:51 AM (EDT).

Customer Signature

Date

Dealer Signature

Date