

Display CARFAX in online listings:



### History-Based Value Report

#### History events affecting this vehicle's value



Service History



Personal Vehicle



Damage

**\$9,650 Retail Value**



### Vehicle History Report™

US \$44.99

#### 2010 MAZDA MAZDA6 I TOURING

VIN: 1YVHZ8CH9A5M01487  
SEDAN 4 DR  
2.5L I4 F DOHC 16V  
GASOLINE  
FRONT WHEEL DRIVE



Damage reported



27 Service history records



2 Previous owners



Personal vehicle





Last owned in New York



85,684 Last reported odometer reading


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/24/23 at 6:20:05 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Ownership History</b> The number of owners is estimated	Owner 1	Owner 2
Year purchased	2009	2011
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 1 mo.	11 yrs. 6 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	13,237/yr	5,294/yr
Last reported odometer reading	27,854	85,684

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1	Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem




**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.  
View Terms | View Certificate

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Damage reported: 05/23/2023.	<input checked="" type="checkbox"/> No Issues Reported	Damage Reported

<b>Manufacturer Recall</b>	✔ No Recalls Reported	✔ No Recalls Reported
<b>Basic Warranty</b>	Warranty Expired	Warranty Expired
Check with an authorized Mazda dealer for any open recalls.		
Original warranty estimated to have expired.		

**CARFAX** Detailed History

 **Owner 1**  
Purchased: 2009






**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.





Personal Vehicle  
13,237 mi/yr






Date	Mileage	Source	Comments
07/29/2009		NICB	<b>Vehicle manufactured and shipped to original dealer</b>
08/26/2009	5	New York Inspection Station	<b>Emissions inspection performed</b> Dealer had vehicle inspected to prepare it for sale Passed safety inspection
08/27/2009	149	Service Plan Co. Clay, NY	<b>Service contract issued</b>
08/27/2009		New York Motor Vehicle Dept. Clay, NY	<b>Title issued or updated</b> Registration issued or renewed First owner reported Titled or registered as personal vehicle Loan or lien reported Passed safety inspection
09/02/2010	12,973	New York Inspection Station	<b>Emissions inspection performed</b> Passed safety inspection
08/10/2011		New York Motor Vehicle Dept. Clay, NY	<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
09/29/2011	27,820	New York Inspection Station	<b>Passed safety inspection</b> Emissions inspection performed
10/04/2011	27,854	New York Inspection Station	<b>Passed safety inspection</b> Emissions inspection performed
10/05/2011		Dealer Inventory	<b>Vehicle offered for sale</b>





10/20/2011	New York Motor Vehicle Dept. Cicero, NY	<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
------------	---	---





 <b>Owner 2</b> Purchased: 2011		<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 5,294 mi/yr
---	---	---	---------------------------------

Date	Mileage	Source	Comments
11/10/2011		New York Motor Vehicle Dept. Cicero, NY	<b>Title issued or updated</b> New owner reported
11/22/2011		New York Motor Vehicle Dept. Syracuse, NY	<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection Registration updated when owner moved the vehicle to a new location
10/22/2012	32,685	New York Inspection Station	<b>Passed safety inspection</b> Passed emissions inspection
06/07/2013		New York Motor Vehicle Dept. Syracuse, NY	<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
10/08/2013	37,353	New York Inspection Station	<b>Passed safety inspection</b> Passed emissions inspection
10/10/2014	43,459	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ❤️ 4 Customer Favorites	 <b>Vehicle serviced</b> Emissions or safety inspection performed
10/10/2014		New York Inspection Station	<b>Passed safety inspection</b> Passed emissions inspection





11/26/2014	43,943	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Tires rotated
02/11/2015	44,225	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Wiper(s) replaced
05/21/2015		New York Motor Vehicle Dept. Syracuse, NY		<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
06/16/2015	46,426	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
10/22/2015	48,841	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Tires rotated Emissions or safety inspection performed
10/22/2015		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection






12/07/2015	49,208	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Tire(s) replaced
03/11/2016		G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Wiper(s) replaced
07/01/2016	51,205	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Vehicle washed/detailed Oil and filter changed
10/25/2016	53,532	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Tire repaired Oil and filter changed Emissions or safety inspection performed
10/25/2016		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
11/17/2016	53,744	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Tire(s) replaced

04/13/2017	55,250	G & V Auto Care Liverpool, NY 315-457-5700 napautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Transmission cooler line(s) repaired/replaced
06/07/2017		New York Motor Vehicle Dept. Syracuse, NY		<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
09/11/2017	58,535	G & V Auto Care Liverpool, NY 315-457-5700 napautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Emissions or safety inspection performed
09/11/2017		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
05/04/2018	61,261	G & V Auto Care Liverpool, NY 315-457-5700 napautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
09/17/2018		G & V Auto Care Liverpool, NY 315-457-5700 napautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Emissions or safety inspection performed
09/17/2018		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection

04/10/2019	62,544	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Wiper(s) replaced Oil and filter changed Tires rotated
05/09/2019		New York Motor Vehicle Dept. Brewerton, NY		<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection Registration updated when owner moved the vehicle to a new location
07/01/2019		G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Front brake pads replaced
09/26/2019	69,760	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Emissions or safety inspection performed
09/26/2019		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
03/12/2020	72,264	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed



06/11/2020	72,934	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b>
09/22/2020	74,536	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Daytime running light bulb(s) replaced Oil and filter changed Emissions or safety inspection performed
09/22/2020	75,436	New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
12/22/2020	76,863	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Wiper(s) replaced
06/10/2021		New York Motor Vehicle Dept. Brewerton, NY		<b>Registration issued or renewed</b> Titled or registered as personal vehicle Passed safety inspection
06/14/2021	78,985	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Vehicle washed/detailed


09/13/2021	80,746	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Brakes checked Rear brake pads replaced Emissions or safety inspection performed
09/13/2021	80,749	New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
11/23/2021	81,698	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
08/22/2022	84,199	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
09/16/2022	84,330	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b> Front brake pads replaced Emissions or safety inspection performed
09/16/2022		New York Inspection Station		<b>Passed safety inspection</b> Passed emissions inspection
10/24/2022	85,684	G & V Auto Care Liverpool, NY 315-457-5700 napaautocare.com/store.aspx?id=386576 ★ 5.0 / 5.0 12 Verified Reviews ♥ 4 Customer Favorites		<b>Vehicle serviced</b>

05/23/2023

Damage Report

**Damage reported**

Damage to rear

**CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION**

Not all damage is caused by an accident. Get the car inspected before you buy. [Learn More](#)

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/24/23 at 6:20:05 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

**New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.  
6/24/23 6:20:05 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 MAZDA MAZDA6 vehicle (VIN: 1YVHZ8CH9A5M01487), which is based on information supplied to CARFAX and available as of 6/24/23 at 7:20 AM (EDT).**

Customer Signature

Date

Dealer Signature

Date