



### History-Based Value Report

#### History events affecting this vehicle's value



Service History



Personal Vehicle



Damage

**\$3,550 Retail Value**



### Vehicle History Report™


US \$44.99

**2008 SUBARU  
OUTBACK 2.5I LIMITED**

VIN: 4S4BP62C287344152  
4 DOOR WAGON/SPORT  
UTILITY  
2.5L H4 F SOHC 16V  
GASOLINE  
ALL WHEEL DRIVE



**Minor to moderate damage**



**47** Service history records



**2** Previous owners



Personal vehicle



**192,736** Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/11/24 at 6:29:39 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





### Accident / Damage History

Not all accidents / issues are reported to CARFAX

#### Event 1

06/22/2018

**Damage reported:  
minor to moderate  
damage**



### Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Damage reported: 06/22/2018.	<input checked="" type="checkbox"/> No Issues Reported	Damage Reported
<b>Manufacturer Recall</b> Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired



### Title History

CARFAX guarantees the information in this section

	Owner 1	Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem

**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem

**Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
View Terms | View Certificate



**Ownership History**

The number of owners is estimated

**Owner 1**

**Owner 2**

Year purchased

2008

2010

Type of owner

Personal

Personal

Estimated length of ownership

2 yrs. 7 mo.

13 yrs. 7 mo.

Owned in the following states/provinces

Connecticut

Connecticut

Estimated miles driven per year

17,998/yr

12,529/yr

Last reported odometer reading

43,952

192,736



**Detailed History**



**Owner 1**

Purchased: 2008

Personal Vehicle

17,998 mi/yr

**Date**

**Mileage**

**Source**

**Comments**

01/09/2008 10

Garavel Subaru  
Norwalk, CT  
203-840-1750  
garavelsubaru.com



**Vehicle serviced**

Pre-delivery inspection completed

★ **4.7 / 5.0**  
307 Verified Reviews  
❤ **8** Customer Favorites

02/21/2008 17

Connecticut  
Motor Vehicle Dept.

**Vehicle purchase reported**






Titled or registered as personal vehicle






03/13/2008


Connecticut  
Motor Vehicle Dept.  
Westport, CT  
Title #030930122



**Title issued or updated**




First owner reported






04/26/2008	3,411	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed 3,750 mile service performed Fluids checked Oil and filter changed Tire condition and pressure checked</p>
07/21/2008	7,436	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed 7,500 mile service performed Brakes checked Oil and filter changed Tires rotated Drain plug gasket replaced</p>
09/27/2008	10,841	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed</p>
01/06/2009	14,923	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed 15,000 mile service performed Air filter replaced Fuel filter replaced Fluids checked Transmission fluid changed Oil and filter changed Tire condition and pressure checked Tires rotated</p>
04/08/2009	19,168	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed Exterior lights checked Oil and filter changed Light bulb(s) replaced Tire(s) balanced</p>





07/08/2009	22,899	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed 22,500 mile service performed Two wheel alignment performed Battery/charging system checked Air filter checked Brakes checked Oil and filter changed Tires rotated Drain plug gasket replaced Alignment performed</p>
09/25/2009	27,174	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> Oil and filter changed</p>
12/03/2009	30,849	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed 30,000 mile service performed Wiper(s) replaced Drive belts checked Spark plug(s) replaced Tune-up performed Fluids checked Transmission fluid changed Oil and filter changed Tires rotated Antifreeze/coolant flushed/changed</p>
03/11/2010	35,931	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> Oil and filter changed Headlight bulb(s) replaced</p>
06/03/2010	40,427	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Drive belts adjusted Brakes checked Tires rotated Body lubricated Brake fluid flushed/changed</p>

<p>07/31/2010 43,952</p> <p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Pre-delivery inspection completed Oil and filter changed Engine/powertrain computer/module reprogrammed Cabin air filter replaced/cleaned</p>
---	--






 <p><b>Owner 2</b> Purchased: 2010</p>		<p><b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.</p>	<p>Personal Vehicle 12,529 mi/yr</p>
---	---	--	--







Date	Mileage	Source	Comments
10/05/2010		Connecticut Motor Vehicle Dept.	<b>Vehicle purchase reported</b> Registration issued or renewed Vehicle color noted as Tan
10/28/2010		Connecticut Motor Vehicle Dept. Stamford, CT Title #032379315	<b>Title issued or updated</b> New owner reported
11/13/2010 49,899	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com	 <p><b>Vehicle serviced</b> Engine/powertrain computer/module checked Fluids checked Oil and filter changed Tire condition and pressure checked</p>	<p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>
12/21/2010 52,804	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com	 <p><b>Vehicle serviced</b> Emission system checked Catalytic converter replaced</p>	<p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>
02/05/2011 55,272	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com	 <p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Battery/charging system checked Drivability/performance checked Brakes checked Fluids checked Oil and filter changed Wiper(s) replaced Lights checked</p>	<p>★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites</p>






04/09/2011	58,650	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Drivability/performance checked Oil and filter changed
04/18/2011		Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Spark plug(s) replaced Battery serviced Brakes checked Tune-up performed Oil and filter changed Tires rotated Transmission serviced
08/16/2011	67,495	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Fluids checked Oil and filter changed Engine/powertrain computer/module reprogrammed Tire condition and pressure checked
11/22/2011	73,827	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Fluids checked Oil and filter changed Tire condition and pressure checked
03/17/2012	81,849	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Trailing arm bushing(s) replaced Control arm bushing(s) replaced Power steering fluid flushed/changed Light bulb(s) replaced Drive belts checked Drivability/performance checked Brakes checked Oil and filter changed Battery serviced Fluids checked Timing belt replaced Lower control arm bushings replaced Lights checked

11/10/2012 95,926	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Wipers/washers checked Drivability/performance checked Oil and filter changed Battery serviced Brakes checked Battery/charging system checked Valve cover gasket(s) replaced Wiper(s) replaced
11/23/2012	Connecticut Motor Vehicle Dept. Stamford, CT		<b>Registration issued or renewed</b> Vehicle color noted as Tan
01/12/2013 98,800	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com		<b>Vehicle serviced</b> Engine/powertrain computer/module checked Fluids checked Oil and filter changed Tire condition and pressure checked Spark plug wires replaced
05/24/2013 104,308	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Drivability/performance checked Brakes checked Oil and filter changed Battery serviced Engine/powertrain computer/module reprogrammed Catalytic converter replaced
09/21/2013 111,249	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com		<b>Vehicle serviced</b> Maintenance inspection completed Fluids checked Oil and filter changed Tire condition and pressure checked




11/16/2013	114,667	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Axle(s) replaced
04/05/2014	121,857	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Drivability/performance checked Oil and filter changed Battery serviced Brakes checked Rear wheel bearing(s)/hub(s) replaced
04/26/2014	123,320	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Engine/powertrain computer/module checked
09/23/2014	125,250	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Lights checked
10/17/2014		Connecticut Motor Vehicle Dept. Stamford, CT		<b>Registration issued or renewed</b> Vehicle color noted as Tan
12/26/2014	127,121	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Tires rotated Brakes replaced


05/18/2015	144,048	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed 15,000 mile service performed Drive belt(s) replaced Tail light bulb(s) replaced Brakes checked
09/15/2015	150,298	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Key(s) (re) programmed
10/07/2015	152,081	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Battery replaced Front strut(s) replaced
02/23/2016	156,507	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed
06/27/2016	159,092	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed 30,000 mile service performed Light bulb(s) replaced Heat shield secured Brakes checked Tire(s) balanced Four tires balanced
07/14/2016	159,242	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ 4.7 / 5.0 307 Verified Reviews ❤️ 8 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Brakes checked




08/17/2016		Connecticut Motor Vehicle Dept. Stamford, CT Title #032379315		<b>Registration issued or renewed</b> Vehicle color noted as Tan
09/07/2016	160,145	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites		<b>Vehicle serviced</b> Wheel lug stud(s) replaced Brakes checked
11/16/2016	161,547	Connecticut Inspection Station Stamford, CT		<b>Passed emissions inspection</b>
02/17/2017	163,032	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Wiper(s) replaced
05/23/2017	165,181	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Wiper(s) replaced Rear wiper blade replaced
04/25/2018	168,549	Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com ★ <b>4.7 / 5.0</b> 307 Verified Reviews ❤️ <b>8</b> Customer Favorites		<b>Vehicle serviced</b> Recommended maintenance performed Tire condition and pressure checked
06/22/2018		Damage Report		<b>Damage reported: minor to moderate damage</b> Damage to left front Damage to front Damage to left side







**CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION**



07/16/2018	170,766	Connecticut Inspection Station Stamford, CT	<b>Passed emissions inspection</b>
08/13/2018		Connecticut Motor Vehicle Dept. Stamford, CT Title #032379315	<b>Registration issued or renewed</b> Vehicle color noted as Tan
08/21/2018	171,815	Maguire Subaru Hyundai Ithaca, NY 866-268-8490 maguiresubaru.com/ index.htm ★ <b>4.3 / 5.0</b> 20 Verified Reviews ♥ <b>420</b> Customer Favorites	 <b>Vehicle serviced</b> Cooling system serviced Four tires balanced Four tires mounted Four wheel alignment performed Alignment performed

01/14/2019 174,541	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ♥ 8 Customer Favorites</p>		<p><b>Vehicle serviced</b> 60,000 mile service performed Sway bar bushing(s) replaced Spark plug(s) replaced Air filter replaced Brakes checked Fluids checked Differential fluid flushed/changed Oil and filter changed Brake fluid flushed/changed Tire condition and pressure checked Tires rotated Heat shield secured Stabilizer bar bushings replaced Battery replaced Induction system serviced Fuel system cleaned/serviced Cabin air filter replaced/cleaned</p>
12/04/2019	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ♥ 8 Customer Favorites</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed 7,500 mile service performed Rear brake pads replaced Rear brake rotor(s) replaced Drive belts checked Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Tires rotated</p>
07/01/2020	<p>Garavel Subaru Norwalk, CT 203-840-1750 garavelsubaru.com</p> <p>★ 4.7 / 5.0 307 Verified Reviews ♥ 8 Customer Favorites</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed 7,500 mile service performed Front brake rotor(s) replaced Front brake pads replaced Drive belts checked Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Tires rotated</p>
07/13/2020 183,873	<p>Connecticut Inspection Station Stamford, CT</p>		<p><b>Passed emissions inspection</b></p>
08/24/2020	<p>Connecticut Motor Vehicle Dept. Stamford, CT Title #032379315</p>		<p><b>Registration issued or renewed</b> Vehicle color noted as Tan</p>

01/14/2021	186,818	Midas Ithaca, NY 607-272-6312 midas.com ★ <b>4.4 / 5.0</b> 39 Verified Reviews ♥ <b>70</b> Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Tires rotated Brakes checked Fluids checked
02/23/2021	187,039	Maguire Subaru Hyundai Ithaca, NY 866-268-8490 maguiresubaru.com/ index.htm ★ <b>4.3 / 5.0</b> 20 Verified Reviews ♥ <b>420</b> Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Wiper(s) replaced
03/16/2021	187,349	Maguire Subaru Hyundai Ithaca, NY 866-268-8490 maguiresubaru.com/ index.htm ★ <b>4.3 / 5.0</b> 20 Verified Reviews ♥ <b>420</b> Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Engine/powertrain computer/module checked Oil and filter changed
06/30/2021	188,877	Maguire Subaru Hyundai Ithaca, NY 866-268-8490 maguiresubaru.com/ index.htm ★ <b>4.3 / 5.0</b> 20 Verified Reviews ♥ <b>420</b> Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed
04/05/2022	192,736	Connecticut Inspection Station Stamford, CT		<b>Passed emissions inspection</b>
08/18/2022		Connecticut Motor Vehicle Dept. Stamford, CT Title #032379315		<b>Registration issued or renewed</b> Vehicle color noted as Tan

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



**Glossary**

### Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/11/24 at 6:29:39 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://www.facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
5/11/24 6:29:39 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2008 SUBARU OUTBACK vehicle (VIN: 4S4BP62C287344152), which is based on information supplied to CARFAX and available as of 5/11/24 at 7:29 AM (EDT).**

Customer Signature	Date	Dealer Signature	Date
--------------------	------	------------------	------