



History-Based Value Report

\$3,960

CARFAX Retail Value

History events affecting this vehicle's value

- No Accidents Reported
- 1-Owner Vehicle
- Service History
- Personal Vehicle



Vehicle History Report™

US \$44.99

**2004 VOLKSWAGEN
TOUAREG V6**

VIN: WVGBC67L14D010792
4 DOOR WAGON/SPORT
UTILITY
3.2L V6 F
GASOLINE
ALL WHEEL DRIVE

No accidents or damage reported to CARFAX

25 Service history records

CARFAX 1-Owner vehicle

Personal vehicle


Last owned in Massachusetts



112,473 Last reported odometer reading





[^ Back To Top](#)

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/15/24 at 7:43:47 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

|  Additional History Not all accidents / issues are reported to CARFAX | Owner 1 |
|--|---|
| Total Loss No total loss reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Structural Damage No structural damage reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Airbag Deployment No airbag deployment reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Odometer Check No indication of an odometer rollback. | <input checked="" type="checkbox"/> No Issues Indicated |
| Accident / Damage No accidents or damage reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Manufacturer Recall No open recalls reported to CARFAX. | <input checked="" type="checkbox"/> No Recalls Reported |
| Basic Warranty Original warranty estimated to have expired. | Warranty Expired |

|  Title History CARFAX guarantees the information in this section | Owner 1 |
|---|---|
| Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon | <input checked="" type="checkbox"/> Guaranteed No Problem |
| Odometer Brands Not Actual Mileage Exceeds Mechanical Limits | <input checked="" type="checkbox"/> Guaranteed No Problem |
|  GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate | |

|  Ownership History The number of owners is estimated | Owner 1 |
|---|--|
| Year purchased | 2003 |
| Type of owner | Personal |
| Estimated length of ownership |  |

[^ Back To Top](#)

| | |
|---|---------------|
| Owned in the following states/provinces | Massachusetts |
| Estimated miles driven per year | 7,267/yr |
| Last reported odometer reading | 112,473 |

CARFAX Detailed History



Owner 1
Purchased: 2003










Low mileage! This owner drove less than the industry average of 15,000 miles per year.





Personal Vehicle
7,267 mi/yr

| Date | Mileage | Source | Comments |
|------------|---------|--|---|
| 08/15/2003 | | NICB | Vehicle manufactured and shipped to original dealer |
| 08/15/2003 | | Dealer Inventory Massachusetts | Vehicle sold |
| 08/15/2003 | 31 | Massachusetts Motor Vehicle Dept. | Vehicle purchase reported Titled or registered as personal vehicle |
| 08/18/2003 | 37 | Massachusetts Inspection Station Norwood, MA | Passed safety or emissions inspection |
| 08/21/2003 | 90 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews | Vehicle serviced Pre-delivery inspection completed Engine/powertrain computer/module checked Body computer/module reprogrammed Vehicle washed/detailed |
| 09/05/2003 | | Massachusetts Motor Vehicle Dept. West Roxbury, MA Title #AZ344123 | Title or registration issued First owner reported |
| 10/09/2003 | 2,205 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews | Vehicle serviced Drivability/performance checked Engine/powertrain computer/module checked |
| 11/26/2003 | 2,866 | Service Facility | Vehicle serviced |






[^ Back To Top](#)

| | | | | |
|------------|--------|--|---|--|
| 11/26/2003 | | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced |
| 05/07/2004 | 7,113 | Service Facility |  | Vehicle serviced |
| 05/07/2004 | | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Maintenance inspection completed Console repaired Engine/powertrain computer/module checked Rear door trim panel replaced/ repaired Fender liner adjusted/secured Body computer/module replaced |
| 08/18/2004 | 8,636 | Service Facility |  | Vehicle serviced |
| 09/02/2004 | | Massachusetts Inspection Station West Roxbury, MA | | Passed safety or emissions inspection |
| 09/29/2004 | 8,753 | Service Facility |  | Vehicle serviced Drivability/performance checked One wheel replaced Wheel(s) replaced Two tires mounted Front brake pads replaced Rear brake pads replaced |
| 09/29/2004 | | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Rear brake pads replaced Front brake pads replaced Drivability/performance checked One wheel replaced Wheel(s) replaced Two tires mounted |
| 04/07/2005 | | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Rear brake pads replaced Wheel(s) replaced Two tires mounted Door trim panel replaced/repared |
| 10/05/2005 | 19,799 | Massachusetts Inspection Station Norwood, MA | | Passed safety inspection |





[^ Back To Top](#)

| | | | |
|-------------------|--|---|--|
| 10/06/2005 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Maintenance inspection completed Vehicle washed/detailed Drive belts adjusted Battery serviced Oil and filter changed Tires rotated Emissions or safety inspection performed |
| 06/22/2006 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Recommended maintenance performed Radio installed Radio removed Radio replaced Console replaced Wiper(s) replaced Four tires mounted Front brake rotor(s) replaced Front brake pads replaced Brake rotor(s) replaced Fluids checked Oil and filter changed Tire condition and pressure checked Vehicle washed/detailed |
| 11/02/2006 31,900 | Massachusetts Inspection Station West Roxbury, MA | | Passed safety inspection Passed emissions inspection |
| 02/01/2007 | Massachusetts Motor Vehicle Dept. West Roxbury, MA Title #AZ344123 | | Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Green |
| 08/24/2007 39,406 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Maintenance inspection completed Instrument cluster checked Instrument cluster reprogrammed Vehicle washed/detailed Four wheel alignment performed Alignment checked Alignment performed |
| 09/07/2007 39,794 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Cup holder replaced Drivability/performance checked Interior trim repaired Ignition coil(s) replaced |


[^ Back To Top](#)

| | | | | |
|------------|--------|--|---|---|
| 11/15/2007 | 41,316 | Brookline Volkswagen Audi Brookline, MA 617-734-2020 vwofbrookline.com/ en_US/ |  | Vehicle serviced Tire repaired |
| 12/06/2007 | 42,300 | Massachusetts Inspection Station West Roxbury, MA | | Passed safety inspection |
| 07/31/2008 | 47,246 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Drivability/performance checked Driveshaft checked |
| 12/26/2008 | 50,100 | Massachusetts Inspection Station West Roxbury, MA | | Passed safety inspection Passed emissions inspection |
| 02/01/2009 | | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | | Registration issued or renewed Vehicle color noted as Green |
| 03/28/2009 | 51,828 | Brookline Volkswagen Audi Brookline, MA 617-734-2020 vwofbrookline.com/ en_US/ |  | Vehicle serviced 50,000 mile service performed |
| 08/26/2009 | 54,014 | Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com ★ 4.6 / 5.0 39 Verified Reviews |  | Vehicle serviced Maintenance inspection completed Drive belts adjusted Battery serviced Oil and filter changed Tires rotated Vehicle washed/detailed |
| 11/12/2009 | 55,794 | Brookline Volkswagen Audi Brookline, MA 617-734-2020 vwofbrookline.com/ en_US/ |  | Vehicle serviced Four tires balanced Four tires mounted Four wheel alignment performed |
| 01/04/2010 | 56,339 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |


[^ Back To Top](#)

| | | | |
|------------|--------|---|---|
| 11/02/2010 | 61,656 | <p>Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com</p> <p>★ 4.6 / 5.0 39 Verified Reviews</p> |  <p>Vehicle serviced Maintenance inspection completed Headlight bulb(s) replaced Wiper(s) replaced Front brake rotor(s) replaced Front brake pads replaced Drive belts adjusted Battery serviced Oil and filter changed Tires rotated Headlight(s) replaced Coolant temperature sensor replaced Brake rotor(s) replaced</p> |
| 02/01/2011 | | <p>Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123</p> | <p>Registration issued or renewed Vehicle color noted as Green</p> |
| 02/19/2011 | 63,045 | <p>Massachusetts Inspection Station Brookline, MA</p> | <p>Passed safety inspection Passed emissions inspection</p> |
| 08/05/2011 | 66,256 | <p>Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com</p> <p>★ 4.6 / 5.0 39 Verified Reviews</p> |  <p>Vehicle serviced 70,000 mile service performed Battery serviced Fluids checked Airbag system checked Brakes checked Tires rotated Oil and filter changed Air filter replaced Shift interlock system checked</p> |
| 11/16/2011 | 67,422 | <p>Brookline Volkswagen Audi Brookline, MA 617-734-2020 vwofbrookline.com/ en_US/</p> |  <p>Vehicle serviced Vehicle washed/detailed</p> |
| 02/03/2012 | 69,275 | <p>Volkswagen Gallery Norwood, MA 781-762-6820 vwgallery.com</p> <p>★ 4.6 / 5.0 39 Verified Reviews</p> |  <p>Vehicle serviced Maintenance inspection completed Front window regulator(s) replaced Engine checked</p> |
| 02/06/2012 | 69,320 | <p>Massachusetts Inspection Station Brookline, MA</p> | <p>Passed safety inspection Passed emissions inspection</p> |

[^ Back To Top](#)

| | | | | |
|------------|---------|--|---|---|
| 02/01/2013 | | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | | Registration issued or renewed Vehicle color noted as Green |
| 03/21/2013 | 75,935 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |
| 04/09/2014 | 83,680 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |
| 02/01/2015 | | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | | Registration issued or renewed Vehicle color noted as Green |
| 05/01/2015 | 91,177 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Failed emissions inspection |
| 12/13/2016 | 100,166 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |
| 02/11/2017 | | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | | Registration issued or renewed Vehicle color noted as Green |
| 03/10/2017 | 101,466 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |
| 03/22/2018 | 108,716 | Boston Volkswagen Watertown, MA 617-783-1300 bostonvw.com ★ 4.6 / 5.0 188 Verified Reviews ❤️ 379 Customer Favorites |  | Vehicle serviced |
| 03/30/2018 | 108,857 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection Passed emissions inspection |
| 01/30/2019 | 112,473 | Massachusetts Inspection Station Brookline, MA | | Passed safety inspection |

[^ Back To Top](#)

| | | |
|------------|---|---|
| 02/01/2019 | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | Registration issued or renewed Vehicle color noted as Green |
| 02/26/2021 | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | Registration issued or renewed Vehicle color noted as Green |
| 02/01/2023 | Massachusetts Motor Vehicle Dept. Brookline, MA Title #AZ344123 | Registration issued or renewed Vehicle color noted as Green |
| 09/08/2023 | Performance Plus Auto And Fabrication Kalamazoo, MI 269-365-9020 performanceplusautofab rication.com/ ★ 5.0 / 5.0 5 Verified Reviews |  Vehicle serviced Battery replaced Battery cable terminal end(s) replaced Battery/charging system checked |

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFO IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EX ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A

[^ Back To Top](#)

PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
12/15/24 7:43:47 AM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2004 VOLKSWAGEN TOUAREG vehicle (VIN: WVGBC67L14D010792), which is based on information supplied to CARFAX and available as of 12/15/24 at 8:43 AM (EST).

Customer Signature

Date

Dealer Signature

Date

[^ Back To Top](#)