



Vehicle History Report™

US \$44.99

2005 VOLVO V50 T5

VIN: YV1MJ682452077581
 WAGON 4 DR
 2.5L I5 F DOHC
 GASOLINE
 ALL WHEEL DRIVE



Accident reported



35 Service history records



CARFAX 1-Owner vehicle



Personal vehicle



Last owned in New York



102,588 Last reported odometer reading

CARFAX HAS THE MOST
 ACCIDENT & DAMAGE
 INFORMATION



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/1/25 at 9:55:03 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

12/17/2009

Accident reported

- It hit a deer

Event 2



12/23/2009

Parts requested for repair:

- Front bumper
- Right fender
- Headlight assembly
- Grille


Event 3

07/10/2023
Damage reported: minor damage



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date	
Oil	✓ Oil and filter changed	09/07/2024	View Details >
Tires	✓ Four tires replaced ✓ Four wheel alignment performed	09/07/2024	View Details >
Brakes	✓ Rear brake pads replaced ✓ Rear brake rotor(s) replaced ✓ Rear brakes replaced	09/07/2024	View Details >
<div><div>This car has been recently serviced. That's a good thing!</div></div>			





CARFAX Additional History





Not all accidents / issues are reported to CARFAX


Owner 1


Total Loss
No total loss reported to CARFAX.

✓ No Issues Reported

Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	 No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	 No Issues Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated
Accident / Damage Accident reported: 12/17/2009. Parts requested for repair: 12/23/2009. Damage reported: 07/10/2023.	Accident Reported
Manufacturer Recall No open recalls reported to CARFAX.	 No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	 Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	 Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2004
Type of owner	Personal
Estimated length of ownership	20 yrs. 7 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	5,180/yr
Last reported odometer reading	102,588

 Detailed History



**Owner 1**






Purchased: 2004



















Low mileage! This owner drove less than the industry average of 15,000 miles per year.






Personal Vehicle
5,180 mi/yr







Date	Mileage	Source	Comments
11/02/2004		Volvo Cars of North America, LLC	Vehicle manufactured - Passion red exterior - Dark beige/quartz leather interior
11/17/2004		US Customs	Vehicle exported from - Belgium and imported to - Newark, NJ
11/18/2004		Volvo Motors	Vehicle shipped to original dealer in Mount Kisco, NY
11/23/2004	8	Mount Kisco Volvo Land Rover Mount Kisco, NY 914-241-0400 thepremiercollection.com	Vehicle sold
11/23/2004		New York Motor Vehicle Dept. Millwood, NY	Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Passed safety inspection
11/24/2004		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ❤️ 26 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Electrical system checked - Safety inspection performed
01/10/2005		New York Motor Vehicle Dept. Millwood, NY	Title issued or updated
12/21/2005		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ❤️ 26 Customer Favorites	 Vehicle serviced - 7,500 mile service performed - Body computer/module checked - Engine/powertrain computer/module checked - Ignition switch replaced - Safety inspection performed
12/21/2005	4,152	New York Inspection Station	Emissions inspection performed - Passed safety inspection









01/04/2006		New York Motor Vehicle Dept. Millwood, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
07/28/2006		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ♥ 26 Customer Favorites	 Vehicle serviced - A/C refrigerant recharged - Computer reprogrammed - Engine/powertrain computer/module checked - Engine/powertrain computer/module reprogrammed - Oil and filter changed
08/08/2006		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ♥ 26 Customer Favorites	 Vehicle serviced - A/C and heating control assembly checked - A/C cycling/pressure switch replaced - A/C expansion/orifice valve replaced - A/C refrigerant recharged - A/C service valves replaced - Engine/powertrain computer/module checked - Glove box lock replaced - Washer nozzle(s) replaced
10/26/2006		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ♥ 26 Customer Favorites	 Vehicle serviced - 7,500 mile service performed - Tire(s) balanced - Tires rotated - Wiper(s) replaced
01/24/2007		Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews ♥ 26 Customer Favorites	 Vehicle serviced - Brake calipers cleaned/serviced - CD player/changer reinstalled - Engine/powertrain computer/module reprogrammed
01/24/2007	8,130	New York Inspection Station	Passed safety inspection - Passed emissions inspection
12/11/2007	11,194	Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0	 Vehicle serviced - 15,000 mile service performed - CD player/changer reinstalled - Engine/powertrain computer/module checked - Engine/powertrain computer/module reprogrammed

		62 Verified Reviews  26 Customer Favorites	- Four wheel alignment performed - Vehicle washed/detailed
01/11/2008		New York Motor Vehicle Dept. Millwood, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
12/19/2008	16,850	Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews  26 Customer Favorites	 Vehicle serviced - Recommended maintenance performed - Wiper(s) replaced
12/19/2008	16,852	New York Inspection Station	Passed safety inspection - Passed emissions inspection
12/03/2009	24,639	Jaguar Land Rover Mt. Kisco Mount Kisco, NY 914-244-9080 landrovermtkisco.com/ ★ 4.1 / 5.0 62 Verified Reviews  26 Customer Favorites	 Vehicle serviced - 30,000 mile service performed - Wiper(s) replaced
12/03/2009		New York Inspection Station	Passed safety inspection - Passed emissions inspection
12/17/2009		Damage Report	 Accident reported - It hit a deer
12/23/2009		Damage Report	 Parts requested for repair: - Front bumper - Right fender - Headlight assembly - Grille CARFAX recommends checking these repairs during your pre-purchase inspection.
12/30/2009		New York Motor Vehicle Dept. Millwood, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
12/15/2010	31,704	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/	 Vehicle serviced - Recommended maintenance performed - Front wiper blades/refills replaced - Emissions inspection performed

12/15/2010	31,710	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/01/2011	32,175	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Engine/powertrain computer/module reprogrammed - Oil and filter changed
12/15/2011		Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - 45,000 mile service performed - Front wiper blades/refills replaced - Rear wiper blade replaced - Wiper arm(s) replaced - Wiper(s) replaced - Vehicle washed/detailed
12/15/2011	39,196	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/15/2012		New York Motor Vehicle Dept. Millwood, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/13/2012	45,393	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Oil and filter changed - Vehicle washed/detailed
12/19/2012	47,045	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Wiper(s) replaced - Vehicle washed/detailed
12/19/2012		New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/25/2013	48,082	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Four wheel alignment performed - License plate light bulb(s) replaced - Vehicle washed/detailed
06/13/2013	50,863	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Vehicle washed/detailed
08/14/2013	51,893	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Throttle body cleaned/serviced - Vehicle washed/detailed
12/12/2013	54,424	New York Inspection Station		Passed safety inspection - Emissions inspection performed

12/13/2013	54,425	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Recommended maintenance performed - Fuel pressure sensor replaced - Vehicle washed/detailed
12/30/2013		New York Motor Vehicle Dept. Millwood, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
07/01/2014	58,493	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - 60,000 mile service performed - Rear brake rotor(s) replaced - Tire repaired - Vehicle washed/detailed
07/17/2014		New York Motor Vehicle Dept. Mount Kisco, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
12/23/2014		Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Oil and filter changed - Vehicle washed/detailed
12/23/2014	61,280	New York Inspection Station		Passed safety inspection - Passed emissions inspection
12/18/2015	67,355	New York Inspection Station		Passed safety inspection - Passed emissions inspection
12/21/2015		Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Recommended maintenance performed - 67,500 mile service performed - Floor mats installed - Four tires balanced - Four tires mounted - Four tires replaced - Four wheel alignment performed - Tire(s) balanced - Tire(s) mounted - Vehicle washed/detailed
02/01/2016		New York Motor Vehicle Dept. Mount Kisco, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
12/22/2016		Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - 75,000 mile service performed - Vehicle washed/detailed

12/22/2016	74,035	New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/10/2017		Auto Center Chappaqua, NY 914-244-5136 autocentercc.com/ ★ 5.0 / 5.0 115 Verified Reviews ❤️ 408 Customer Favorites		Vehicle serviced
01/17/2017	74,373	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Battery cable(s) replaced - Vehicle washed/detailed
05/18/2017	76,747	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Vehicle washed/detailed
12/11/2017	80,919	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Recommended maintenance performed - Front brake pads replaced - Front brake rotor(s) replaced - Vehicle washed/detailed
12/11/2017		New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/08/2018		New York Motor Vehicle Dept. Mount Kisco, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
10/19/2018	85,940	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced - Maintenance inspection completed - Alternator replaced - Coolant reservoir replaced - Oil and filter changed - Tire(s) balanced - Tires rotated - Turn signal switch replaced - Wipers/washers checked - Vehicle washed/detailed
11/23/2018	86,680	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/		Vehicle serviced
12/26/2018	87,349	New York Inspection Station		Passed safety inspection - Failed emissions inspection



01/02/2019	87,501	New York Inspection Station	Passed safety inspection - Failed emissions inspection
01/07/2019	87,590	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/	 Vehicle serviced - Maintenance inspection completed - Emissions inspection performed
01/07/2019	87,625	New York Inspection Station	Passed safety inspection - Passed emissions inspection
05/29/2019	89,308	Mount Kisco Volvo Mount Kisco, NY 914-241-0400 mtkiscovolvo.com/	 Vehicle serviced - Maintenance inspection completed - Exhaust system replaced - Front brake rotor(s) replaced - Rear brake pads replaced - Rear brake rotor(s) replaced - Wipers/washers checked
12/25/2019		New York Motor Vehicle Dept. Mount Kisco, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
01/07/2020	93,999	New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/09/2020		Auto Center Chappaqua, NY 914-244-5136 autocentercc.com/  5.0 / 5.0 115 Verified Reviews  408 Customer Favorites	 Vehicle serviced - Emissions inspection performed - Safety inspection performed
01/29/2021	96,990	New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/26/2021	98,525	Volvo Cars of White Plains Elmsford, NY 844-877-6569 volvocarswhiteplains.com  4.5 / 5.0 299 Verified Reviews  574 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Noise checked - Oil and filter changed - Tire condition and pressure checked - Wiper(s) replaced - Vehicle washed/detailed
01/03/2022		New York Motor Vehicle Dept. Mount Kisco, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
02/11/2022	98,979	New York Inspection Station	Passed safety inspection - Passed emissions inspection

03/31/2023 99,753

New York
Inspection Station**Passed safety inspection**
- Passed emissions inspection

07/10/2023

Damage Report

**Damage reported: minor damage**
- Damage to right front**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION****Damage Severity Scale****Damage Location**

11/01/2023 100,047

Volvo Cars of White
Plains
Elmsford, NY
844-877-6569
volvocarswhiteplains.co
m

★ 4.5 / 5.0

299 Verified Reviews

❤ 574 Customer Favorites

**Vehicle serviced**- Maintenance inspection completed
- Vehicle washed/detailed

12/22/2023

New York
Motor Vehicle Dept.
Mount Kisco, NY**Registration issued or renewed**- Titled or registered as personal vehicle
- Passed safety inspection

01/09/2024 100,172


Volvo Cars of White
Plains
Elmsford, NY
844-877-6569
volvocarswhiteplains.co
m

★ 4.5 / 5.0

299 Verified Reviews

**Vehicle serviced**- Maintenance inspection completed
- Vehicle washed/detailed



03/13/2024	100,696	New York Inspection Station	Passed safety inspection - Passed emissions inspection
09/07/2024	102,588	Volvo Cars of White Plains Elmsford, NY 844-877-6569 volvocarswhiteplains.co m ★ 4.5 / 5.0 299 Verified Reviews ♥ 574 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Four tires balanced - Four tires mounted - Four tires replaced - Four wheel alignment performed - Oil and filter changed - Rear brake pads replaced - Rear brake rotor(s) replaced - Rear brakes replaced - Rear shock absorber(s) replaced - Sway bar link(s) replaced - Vehicle washed/detailed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/1/25 at 9:55:03 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/1/25 at 9:55:03 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.
7/1/25 9:55:03 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2005 VOLVO V50 vehicle (VIN: YV1MJ682452077581), which is based on information supplied to CARFAX and available as of 7/1/25 at 10:55 AM (EDT).

Customer Signature

Date

Dealer Signature

Date