




Report

US \$44.99

1981 Datsun 280ZX GL Turbo


71,237 mi | VIN: JN1CZ04S5BX607023


Hatchback 2 DR | 2.8L I6 F | Gasoline | Rear wheel drive



NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

 **4 Service History Records**

 **22 Detailed Records Available**

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/27/26 at 7:13:03 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History <small>Not all accidents / issues are reported to CARFAX</small>	Summary
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Datsun dealer for any open recalls.	Ask Your Dealer
Basic Warranty No data reported to CARFAX.	No Data Reported

CARFAX Title History	Summary
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem




Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

No Problem

**Detailed History**

Date	Mileage	Source		Comments
10/06/1992		Illinois Inspection Station Chicago, IL		Passed emissions inspection
09/04/1993		Illinois Inspection Station Chicago, IL		Passed emissions inspection
09/17/1994		Illinois Inspection Station Chicago, IL		Passed emissions inspection
09/06/1995		Illinois Inspection Station Chicago, IL		Passed emissions inspection
09/06/1997	60,000	Illinois Inspection Station Chicago, IL		Passed emissions inspection
09/03/1999	64,000	Illinois Inspection Station Chicago, IL		Passed emissions inspection
07/21/2001		Illinois Inspection Station Chicago, IL		Passed emissions inspection
07/12/2003	65,000	Illinois Inspection Station Chicago, IL		Passed emissions inspection
07/28/2005	65,456	Continental Nissan Countryside, IL 708-352-9200 continentalnissan.com ★ 4.4 / 5.0 122 Verified Reviews		Vehicle serviced Fuel injection system checked
08/05/2005		Illinois Inspection Station Chicago, IL		Passed emissions inspection
10/02/2008		Illinois Motor Vehicle Dept. Palos Hills, IL		Registration issued or renewed
10/22/2009		Illinois Motor Vehicle Dept. Palos Hills, IL		Registration issued or renewed Registration updated when owner moved the vehicle to a new location
05/04/2010		Wisconsin Motor Vehicle Dept. Colgate, WI Title #10124Q70066		Title issued or updated New owner reported Exempt from odometer reporting Vehicle color noted as Black
06/21/2010		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Title issued or updated
06/01/2011		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Registration issued or renewed Passed safety inspection Vehicle color noted as Black

07/08/2011		Nissan Of Lewisville - New Owner Lewisville, TX 972-236-5942 nissanoflewisville.com ★ 4.2 / 5.0 89 Verified Reviews ♥ 9,500 Customer Favorites		Vehicle serviced Battery/charging system checked
06/01/2012		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Registration issued or renewed Passed safety inspection Vehicle color noted as Black
06/01/2013		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Registration issued or renewed Passed safety inspection Vehicle color noted as Black
10/03/2013	70,507	Kwik Kar Lube & Tune Of Flower Mound Flower Mound, TX 972-355-1990 ★ 4.7 / 5.0 157 Verified Reviews ♥ 63 Customer Favorites		Vehicle serviced Inspection completed Maintenance inspection completed Safety inspection performed
06/01/2014		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Registration issued or renewed Passed safety inspection Vehicle color noted as Black
10/27/2014	71,237	Kwik Kar Lube & Tune Of Flower Mound Flower Mound, TX 972-355-1990 ★ 4.7 / 5.0 157 Verified Reviews ♥ 63 Customer Favorites		Vehicle serviced Safety inspection performed
06/01/2015		Texas Motor Vehicle Dept. Flower Mound, TX Title #06132740338121150		Registration issued or renewed Passed safety inspection Vehicle color noted as Black

Hmm, we haven't received any information on this car since June 2015. Before you buy, ask the seller for recent service or repair records.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
6/27/26 7:13:03 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1981 DATSUN 280ZX vehicle (VIN: JN1CZ04S5BX607023), which is based on information supplied to CARFAX and available as of 6/27/26 at 8:13 AM (EDT).

<hr/>	<hr/>	<hr/>	<hr/>
Customer Signature	Date	Dealer Signature	Date