


CARFAX History-Based Value Report





This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/16/24 at 5:54:41 PM (CDT). Other information about this vehicle, including problems, may not have been reported to

CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage Accident reported: 08/28/2021.	No Issues Reported	Accident Reported
Manufacturer Recall No open recalls reported to CARFAX.	No Recalls Reported	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired
CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits







GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2012	2019
Type of owner	Personal	Personal
Estimated length of ownership	6 yrs. 9 mo.	5 yrs. 4 mo.
Owned in the following states/provinces	See Details	Illinois
Estimated miles driven per year	13,391/yr	9,976/yr
Last reported odometer reading	91,464	135,659

CARFAX Detailed History

Owner Purcha	r 1 ased: 2012	CAR	Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 13,391 mi/yr
Date	Mileage	Source	Comments	
Not		NICB	Vehicle manufact	tured and shipped to

Reported		Texas
05/07/2012	Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com definition to the second second to the second second second to the second s	Vehicle offered for sale
05/08/2012 132	Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com 4.0 / 5.0 8 Verified Reviews	Vehicle sold


	Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com to define the second second 8 Verified Reviews	╳	Vehicle serviced Emissions or safety inspection performed
2,007	Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com 1.0 / 5.0 8 Verified Reviews	×	Vehicle serviced Fuel system checked
	Texas Motor Vehicle Dept. Willis, TX Title #02130041077153602		Title issued or updated First owner reported Titled or registered as personal vehicle Vehicle color noted as Silver
11,936	Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com t 4.0 / 5.0 8 Verified Reviews	×	Vehicle serviced 10,000 mile service performed Body electrical system checked
21,736	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com t 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced 20,000 mile service performed Vehicle washed/detailed Cabin air filter replaced/cleaned
	Texas Motor Vehicle Dept. Willis, TX Title #02130041077153602		Registration issued or renewed Passed safety inspection Vehicle color noted as Silver
24,891	Lithia Volkswagen Audi of Des Moines Johnston, IA 515-253-0333 lithia.com ★ 4.3 / 5.0 194 Verified Reviews ♥ 590 Customer Favorites	×	Vehicle serviced Maintenance inspection completed Tire condition and pressure checked
	2,007 11,936 21,736 24,891	Bryan, TX 979-776-7600 garlynshelton.com ★ 4.0 / 5.0 8 Verified Reviews2,007Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com ★ 4.0 / 5.0 8 Verified Reviews2,007Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com ★ 4.0 / 5.0 8 Verified Reviews11,936Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com ★ 4.0 / 5.0 8 Verified Reviews21,736Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews21,736Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews24,891Lithia Volkswagen Audi of Des Moines Johnston, IA S15-253-0333 lithia.com ★ 4.3 / 5.0 194 Verified Reviews	Bryan, TX 979-776-7600 garlynshelton.com \star 4.0 / 5.0 8 Verified Reviews2,007Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com \star 4.0 / 5.0 8 Verified Reviews2,007Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com \star 4.0 / 5.0 8 Verified Reviews11,936Garlyn Shelton Imports Bryan, TX 979-776-7600 garlynshelton.com \star 4.0 / 5.0 8 Verified Reviews21,736Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com \star 4.1 / 5.0 42 Verified Reviews21,736Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com \star 4.1 / 5.0 42 Verified Reviews24,891Lithia Volkswagen Audi of Des Moines Johnston, IA 515-253-0333 lithia.com \star 4.3 / 5.0 194 Verified Reviews

08/08/2013	30,004	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com	×	Vehicle serviced 30,000 mile service performed Vehicle washed/detailed
08/29/2013	30,389	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com 1 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Vehicle washed/detailed Headlights adjusted Headlight(s) replaced Grille replaced/repaired
04/03/2014	41,524	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Spark plug(s) replaced Air filter replaced Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Tires rotated Airbag system checked Vehicle washed/detailed Cabin air filter replaced/cleaned
06/01/2014		Texas Motor Vehicle Dept. Willis, TX Title #02130041077153602		Registration issued or renewed Passed safety inspection Vehicle color noted as Silver
08/27/2014	49,609	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Tires rotated Airbag system checked
01/16/2015	54,738	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Computer reprogrammed Engine checked Engine/powertrain computer/module checked

02/09/2015	55,623	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Fuel tank removed and reinstalled Tail light bulb(s) replaced Drivability/performance checked
04/28/2015	59,085	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Drivability/performance checked Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Tires rotated Airbag system checked Cabin air filter replaced/cleaned
06/01/2015		Texas Motor Vehicle Dept. Willis, TX Title #02130041077153602		Registration issued or renewed Passed safety inspection Vehicle color noted as Silver
09/22/2015	69,540	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Maintenance inspection completed Brakes checked Oil and filter changed Tires rotated
04/15/2016	79,006	Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews	×	Vehicle serviced Air filter replaced
06/01/2016		Texas Motor Vehicle Dept. Willis, TX Title #02130041077153602		Registration issued or renewed Passed safety inspection Vehicle color noted as Silver

09/28/2016 90,20	 Volkswagen of the Woodlands Conroe, TX 936-321-6500 vwofthewoodlands.com ★ 4.1 / 5.0 42 Verified Reviews 	×	Vehicle serviced
04/27/2017 90,4	51 Michigan Motor Vehicle Dept. Auburn Hills, MI Title #609F1162467		Title or registration issued to manufacturer
04/26/2019 91,46	54 Dealer Inventory		Vehicle offered for sale
05/08/2019	Auffenberg Nissan Shiloh, IL 618-624-2277 auffenberg.com 1.2 4.2 / 5.0 276 Verified Reviews 948 Customer Favorites	*	Vehicle serviced Pre-delivery inspection completed Airbag replaced Fluids checked Battery serviced Four tires balanced Four tires mounted Oil and filter changed Brake rotor(s) resurfaced Rear brake rotor(s) resurfaced
05/20/2019	Volkswagen	×	Emissions control software updated EPA approved TDI emissions modification performed Covered by Volkswagen Extended Emissions Warranty
05/25/2019	Illinois Motor Vehicle Dept.		Vehicle purchase reported
05/31/2019	Dealer Inventory		Vehicle offered for sale
06/06/2019	Illinois Motor Vehicle Dept. New Baden, IL		Registration issued or renewed Correction to record
Owner 2 Purchased: 20	19 Low mileage! Th than the industry miles per year.		
Date Milea	age Source		Comments
06/13/2019	Illinois Motor Vehicle Dept. New Baden, IL Title #191646903100		Title issued or updated New owner reported Vehicle color noted as Silver

07/17/2019	94,169	Auffenberg Nissan Shiloh, IL 618-624-2277 auffenberg.com	×	Vehicle serviced Maintenance inspection completed Battery replaced Alternator checked Tire(s) balanced Tires rotated
07/23/2019	94,873	Mission Accomplished Tire and Auto New Baden, IL 618-588-4613 5.0 / 5.0 30 Verified Reviews 5 Customer Favorites	×	Vehicle serviced Four tires balanced Four tires mounted
02/14/2020	108,896	Mission Accomplished Tire and Auto New Baden, IL 618-588-4613 ★ 5.0 / 5.0 30 Verified Reviews ♥ 5 Customer Favorites	╳	Vehicle serviced Tire condition and pressure checked Tires rotated Fluids checked Oil and filter changed
04/02/2020	110,145	Mission Accomplished Tire and Auto New Baden, IL 618-588-4613 5.0 / 5.0 30 Verified Reviews 5 Customer Favorites	×	Vehicle serviced Brake fluid flushed/changed Front brake rotor(s) replaced Brake rotor(s) replaced Front brake pads replaced Fuel filter replaced
04/13/2020	110,343	Mission Accomplished Tire and Auto New Baden, IL 618-588-4613 5.0 / 5.0 30 Verified Reviews 5 Customer Favorites	×	Vehicle serviced Axle(s) replaced
05/20/2021	118,083	Mission Accomplished Tire and Auto New Baden, IL 618-588-4613 ★ 5.0 / 5.0 30 Verified Reviews ♥ 5 Customer Favorites	×	Vehicle serviced Fluids checked Oil and filter changed



Vehicle serviced Drivability/performance checked Cooling system serviced Timing belt replaced Antifreeze/coolant flushed/changed
Registration issued or renewed
e

CARFAX Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/16/24 at 5:54:41 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:

facebook.com/CARFAX

🥑 @CARFAXinc

C About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

@ 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 10/16/24 5:54:41 PM (CDT)

I have reviewed and received a copy of the CARFAX Veh PASSAT vehicle (VIN: 1VWBN7A36CC079007), which is available as of 10/16/24 at 6:54 PM (EDT).	

Customer Signature

Date

Dealer Signature

Date