



### History-Based Value Report

#### History events affecting this vehicle's value



**Service History**



**Personal Vehicle**



**Prior Certified Pre-Owned**



**Accident Reported**

**\$3,880 Retail Value**



### Vehicle History Report™

US \$44.99

**2007 HONDA FIT SPORT**

VIN: JHMGD38667S048676  
 HATCHBACK 4 DR  
 1.5L I4 F SOHC  
 GASOLINE  
 FRONT WHEEL DRIVE



Accident reported



**49** Service history records



**2** Previous owners



Personal vehicle





Last owned in New Hampshire



**236,845** Last reported odometer reading


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/20/24 at 7:09:19 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Ownership History</b> The number of owners is estimated	Owner 1	Owner 2
Year purchased	2007	2009
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 1 mo.	14 yrs. 5 mo.
Owned in the following states/provinces	Massachusetts	Massachusetts, New Hampshire
Estimated miles driven per year	13,461/yr	15,059/yr
Last reported odometer reading	28,567	236,845

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1	Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated

<b>Accident / Damage</b> Accident reported: 02/17/2012.	<input checked="" type="checkbox"/> No Issues Reported	Accident Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check with an authorized Honda dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

**CARFAX** Detailed History








**Owner 1**  
 Purchased: 2007











**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.





Personal Vehicle  
 13,461 mi/yr


Date	Mileage	Source	Comments
06/04/2007		Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites	 <b>Vehicle serviced</b> Pre-delivery inspection completed Cargo cover installed Floor mats installed Emissions or safety inspection performed
06/05/2007	10	Commonwealth Motors Lawrence, MA 978-687-3000 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites	<b>Vehicle sold</b>
06/05/2007		Massachusetts Motor Vehicle Dept.	<b>Vehicle purchase reported</b> Titled or registered as personal vehicle
06/09/2007	123	Massachusetts Inspection Station Lawrence, MA	<b>Passed safety inspection</b>

06/18/2007	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Interior trim checked</p>
06/22/2007	<p>Massachusetts Motor Vehicle Dept. Merrimac, MA Title #BE614526</p>	<p><b>Title issued or updated</b> First owner reported Vehicle color noted as Gray</p>
09/07/2007	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Oil and filter changed</p>
12/01/2007	<p>Massachusetts Motor Vehicle Dept. Merrimac, MA Title #BE614526</p>	<p><b>Registration issued or renewed</b> Vehicle color noted as Gray</p>
12/27/2007	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites</p>	 <p><b>Vehicle serviced</b> Tire(s) balanced Tires rotated Oil and filter changed</p>
02/18/2008	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p>



04/12/2008	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com		<b>Vehicle serviced</b> Oil and filter changed
★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites			
06/17/2008 17,332	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com		<b>Vehicle serviced</b> 10,000 mile service performed Wheels checked Wiper(s) replaced Drivability/performance checked Lights checked Fog light assembly replaced Fog light bulb(s) replaced Emissions or safety inspection performed
★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites			
06/23/2008	Massachusetts Inspection Station Lawrence, MA	<b>Passed safety inspection</b>	
11/06/2008 21,352	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed
★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites			
04/02/2009 25,380	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com		<b>Vehicle serviced</b> Noise checked Four wheel alignment performed Tire(s) balanced Tires rotated
★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites			
06/08/2009 27,588	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com		<b>Vehicle serviced</b> Emissions or safety inspection performed
★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites			

06/08/2009		Massachusetts Inspection Station Lawrence, MA	<b>Passed safety inspection</b> Passed emissions inspection
07/16/2009	28,471	Commonwealth Motors Lawrence, MA 978-683-5000 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites	<b>Vehicle offered for sale</b>
07/23/2009		Honda Certified Dealer Lawrence, MA 	<b>Storm Silver Metallic exterior</b> Black interior
07/26/2009	28,567	Commonwealth Motors Lawrence, MA 978-687-3000 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites	<b>Vehicle sold</b>
 <b>Owner 2</b> Purchased: 2009			Personal Vehicle 15,059 mi/yr
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>
07/26/2009		Massachusetts Motor Vehicle Dept.	<b>Vehicle purchase reported</b>
07/29/2009		Massachusetts Motor Vehicle Dept. Methuen, MA	<b>Registration issued or renewed</b> New owner reported Vehicle color noted as Gray
07/30/2009	28,570	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ♥ 25,195 Customer Favorites	 <b>Vehicle serviced</b> Emissions or safety inspection performed
07/30/2009		Massachusetts Inspection Station Lawrence, MA	<b>Passed safety inspection</b> Passed emissions inspection








08/14/2009		Massachusetts Motor Vehicle Dept. Methuen, MA Title #BH105610		<b>Title issued or updated</b> Vehicle color noted as Gray
04/19/2010	46,919	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
06/24/2010	51,979	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites		<b>Vehicle serviced</b> Wheels checked Wheel locks installed
08/23/2010		New Hampshire Motor Vehicle Dept. Nashua, NH Title #11988997		<b>Title issued or updated</b> Registration issued or renewed Loan or lien reported Registration updated when owner moved the vehicle to a new location Vehicle color noted as Gray
03/02/2011	62,220	Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com ★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
09/28/2011	75,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
09/30/2011		New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Vehicle color noted as Gray
02/17/2012		Damage Report		<b>Accident reported with another motor vehicle</b> Damage to left front













## CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION





10/04/2012		New Hampshire Motor Vehicle Dept. Nashua, NH	<b>Registration issued or renewed</b> Vehicle color noted as Gray
10/05/2012	91,000	New Hampshire Inspection Station Hillsborough County	<b>Passed emissions inspection</b>
01/10/2013	97,637	Peters Honda of Nashua Nashua, NH 603-579-5230 petersauto.com ★ 4.7 / 5.0 557 Verified Reviews ❤️ 5,823 Customer Favorites	 <b>Vehicle serviced</b>
04/03/2013		Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews	 <b>Vehicle serviced</b> Oil and filter changed Brakes checked Tires rotated Brakes serviced
10/01/2013		New Hampshire Motor Vehicle Dept. Nashua, NH	<b>Registration issued or renewed</b> Vehicle color noted as Gray











10/03/2013		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Oil and filter changed Tires rotated Brakes checked Brakes serviced Emissions or safety inspection performed</p>
10/03/2013	107,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Passed emissions inspection</b></p>
11/05/2013		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Tire(s) balanced Alignment checked Tire valve stem(s)/core(s) replaced Four wheel alignment performed Tire(s) replaced</p>
12/06/2013	109,636	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Tire valve stem(s)/core(s) replaced Tire(s) balanced Tire(s) replaced</p>
03/07/2014		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Oil and filter changed Tires rotated Brakes checked Brakes serviced</p>
04/18/2014	115,049	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b></p>
07/05/2014		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Oil and filter changed Brakes checked Tires rotated Brakes serviced Air filter checked</p>
08/20/2014	122,240	<p>Peters Honda of Nashua Nashua, NH 603-579-5230 petersauto.com</p> <p>★ 4.7 / 5.0 557 Verified Reviews ❤️ 5,823 Customer Favorites</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Window switch replaced</p>





10/02/2014		New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Vehicle color noted as Gray
10/09/2014		Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Brakes checked Oil and filter changed Tires rotated Brakes serviced Emissions or safety inspection performed
10/09/2014	124,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
02/28/2015		Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Brakes checked Oil and filter changed Tires rotated Brake pads replaced Brakes serviced
06/29/2015	137,045	Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed Tires rotated Brakes checked Brakes serviced
10/01/2015		New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Registration updated when owner moved the vehicle to a new location Vehicle color noted as Gray
10/31/2015		Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed Brakes checked Tires rotated Brakes serviced Emissions or safety inspection performed
10/31/2015	143,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
01/20/2016	146,336	Monro Auto Service & Tire Centers Merrimack, NH ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Tire(s) balanced Tire valve stem(s)/core(s) replaced Tire(s) replaced Axles checked

04/16/2016	149,463	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b>                      Brakes checked                      Oil and filter changed                      Tires rotated                      Battery/charging system checked                      Brakes serviced                      Tire(s) balanced                      Tire valve stem(s)/core(s) replaced                      Alignment checked                      Tire(s) replaced                      Four wheel alignment performed</p>
05/04/2016	150,331	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b>                      Oil and filter changed                      Brakes checked                      Tires rotated                      Battery/charging system checked                      Brakes serviced</p>
08/26/2016	156,457	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b>                      Oil and filter changed                      Brakes checked                      Tires rotated                      Battery/charging system checked                      Brakes serviced</p>
10/07/2016		<p>New Hampshire Motor Vehicle Dept. Nashua, NH</p>		<p><b>Registration issued or renewed</b>                      Vehicle color noted as Gray</p>
10/22/2016	159,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Failed emissions inspection</b></p>
10/22/2016	159,448	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b>                      Wiper(s) replaced                      Wipers/washers checked                      Emissions or safety inspection performed</p>
12/16/2016	160,902	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b>                      Spark plug(s) replaced</p>
01/26/2017	162,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Passed emissions inspection</b></p>

01/27/2017	162,738	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Oil and filter changed Tires rotated Battery/charging system checked Brakes checked Brakes serviced</p>
03/27/2017	165,525	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ 4.5 / 5.0 1,560 Verified Reviews ❤️ 25,195 Customer Favorites</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Engine/powertrain computer/module checked</p>
06/15/2017	169,144	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Brakes checked Oil and filter changed Tires rotated Battery/charging system checked Brakes serviced</p>
10/31/2017		<p>New Hampshire Motor Vehicle Dept. Nashua, NH</p>		<p><b>Registration issued or renewed</b> Vehicle color noted as Gray</p>
12/16/2017		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH</p> <p>★ 5.0 / 5.0 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Brakes checked Brakes serviced Battery/charging system checked Oil and filter changed Tires rotated Emissions or safety inspection performed</p>
12/16/2017	176,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Passed emissions inspection</b></p>
09/15/2018	188,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Passed emissions inspection</b></p>
10/12/2018		<p>New Hampshire Motor Vehicle Dept. Nashua, NH</p>		<p><b>Registration issued or renewed</b> Vehicle color noted as Gray</p>

02/27/2019	194,173	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH 603-424-1432 monro.com</p> <p>★ <b>5.0 / 5.0</b> 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Brakes checked Battery/charging system checked Oil and filter changed Brakes serviced</p>
09/13/2019		<p>New Hampshire Motor Vehicle Dept. Nashua, NH</p>		<p><b>Registration issued or renewed</b> Vehicle color noted as Gray</p>
09/20/2019	199,000	<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Passed emissions inspection</b></p>
09/21/2019		<p>Monro Auto Service &amp; Tire Centers Merrimack, NH 603-424-1432 monro.com</p> <p>★ <b>5.0 / 5.0</b> 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed</p>
10/09/2019	201,044	<p>Commonwealth Motors Lawrence, MA 978-965-3741 shopuslast.com</p> <p>★ <b>4.5 / 5.0</b> 1,560 Verified Reviews ♥ <b>25,195</b> Customer Favorites</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed</p>
07/24/2020	207,337	<p>Monro Auto Service &amp; Tire Centers Merrimack, NH 603-424-1432 monro.com</p> <p>★ <b>5.0 / 5.0</b> 5 Verified Reviews</p>		<p><b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Antifreeze/coolant flushed/changed</p>
07/25/2020		<p>New Hampshire Inspection Station Hillsborough County</p>		<p><b>Failed emissions inspection</b></p>




08/17/2020	Monro Auto Service & Tire Centers Merrimack, NH 603-424-1432 monro.com		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed
09/25/2020	New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Vehicle color noted as Gray
10/07/2020	Monro Auto Service & Tire Centers Merrimack, NH 603-424-1432 monro.com		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Emissions or safety inspection performed
10/07/2020 208,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
05/14/2021 210,848	Monro Auto Service & Tire Centers Merrimack, NH 603-424-1432 monro.com		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Tire(s) replaced Brakes checked Spark plug(s) replaced Battery/charging system checked Oil and filter changed Engine oil system flushed Alignment checked Brakes serviced Four wheel alignment performed Stabilizer bar links replaced
06/08/2021 211,210	Peters Honda of Nashua Nashua, NH 603-579-5230 petersauto.com		<b>Vehicle serviced</b> Maintenance inspection completed
	★ <b>5.0 / 5.0</b> 5 Verified Reviews ❤️ <b>5,823</b> Customer Favorites		

06/30/2021	211,219	Peters Honda of Nashua Nashua, NH 603-579-5230 petersauto.com ★ 4.7 / 5.0 557 Verified Reviews ❤️ 5,823 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed
09/16/2021	213,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
09/16/2021		New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Vehicle color noted as Gray
08/08/2022	230,000	New Hampshire Inspection Station Hillsborough County		<b>Passed emissions inspection</b>
09/28/2022		New Hampshire Motor Vehicle Dept. Nashua, NH		<b>Registration issued or renewed</b> Vehicle color noted as Gray
03/02/2023		Peters Honda of Nashua Nashua, NH 603-579-5230 petersauto.com ★ 4.7 / 5.0 557 Verified Reviews ❤️ 5,823 Customer Favorites		<b>Vehicle serviced</b>
03/03/2023	233,606	Monro Auto Service & Tire Centers Merrimack, NH 603-424-1432 monro.com ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Battery replaced Drive belt tensioner replaced Drive belts checked Battery/charging system checked
05/26/2023	236,845	Monro Auto Service & Tire Centers Merrimack, NH 603-424-1432 monro.com ★ 5.0 / 5.0 5 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Recommended maintenance performed Oil and filter changed Battery/charging system checked Brakes checked Brakes serviced Tires rotated

12/19/2023	New Hampshire Motor Vehicle Dept. Nashua, NH Title #16923801	<b>Title issued or updated</b> Duplicate title issued Vehicle color noted as Gray
------------	---	---

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).

 **Glossary**

**Follow Us:**  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
1/20/24 7:09:19 AM (CST)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2007 HONDA FIT vehicle (VIN: JHMGD38667S048676), which is based on information supplied to CARFAX and available as of 1/20/24 at 8:09 AM (EST).**

---

<b>Customer Signature</b>	<b>Date</b>	<b>Dealer Signature</b>	<b>Date</b>
---------------------------	-------------	-------------------------	-------------