

**CARFAX** History-Based Value Report

History events affecting this vehicle's value



Service History



Personal Vehicle



Open Recall



Minor Damage

**\$11,410 Retail Value**




Vehicle History Report™

US \$44.99

**2014 FORD EXPLORER XLT**

VIN: 1FM5K7D83EGA22058  
 4 DOOR WAGON/SPORT UTILITY  
 3.5L V6 F DOHC 24V GASOLINE  
 FRONT WHEEL DRIVE  
 Original Window Sticker

Accident reported: minor damage



**36** Service history records

At least 1 open recall

**2** Previous owners

**127,204** Last reported odometer reading



^ Back To Top

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/10/24 at 9:34:48 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



**CARFAX** Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

05/20/2019

**Damage reported:  
minor damage**





Event 2

12/22/2023

**Accident reported:  
minor damage**

It hit a deer  
It hit an animal





**CARFAX** Additional History


Not all accidents / issues are reported to CARFAX




	Owner 1	Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Damage reported: 05/20/2019. Accident reported: 12/22/2023.	<input checked="" type="checkbox"/> No Issues Reported	Minor Damage





Minor Damage  
[^ Back To Top](#)

<b>Manufacturer Recall</b>	<input checked="" type="checkbox"/> No Recalls Reported	Recall Reported
<b>Basic Warranty</b>	Warranty Expired	Warranty Expired





	<b>Title History</b>	
CARFAX guarantees the information in this section		
<b>Damage Brands</b>	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon		
<b>Odometer Brands</b>	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
Not Actual Mileage   Exceeds Mechanical Limits		
		
<b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>		

	<b>Ownership History</b>	
The number of owners is estimated		
Year purchased	2013	2017
Type of owner	Personal lease	Personal
Estimated length of ownership	2 yrs. 8 mo.	7 yrs. 7 mo.
Owned in the following states/provinces	Michigan	Michigan
Estimated miles driven per year	12,143/yr	12,786/yr
Last reported odometer reading	32,505	127,204

				<b>Detailed History</b>	
	<b>Owner 1</b> Purchased: 2013		<div style="border: 1px solid #00aaff; padding: 5px;"> <b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.                 </div>	Personal Lease Vehicle 12,143 mi/yr	
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>		
<span style="border: 1px solid #ccc; border-radius: 15px; padding: 5px 15px; display: inline-block;">^ Back To Top</span>					


08/02/2013	Ford Motor Company		<b>Vehicle manufactured and shipped to original dealer</b>
			Original Window Sticker
08/02/2013	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle offered for sale</b>
08/02/2013 4	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle serviced</b> Pre-delivery inspection completed
08/05/2013	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle sold</b>
08/05/2013 76	Michigan Motor Vehicle Dept. Brooklyn, MI Title #603B2170534		<b>Title or registration issued</b> First owner reported Titled or registered as personal lease vehicle
01/20/2014 5,753	Tire Choice Auto Service Centers Venice, FL ★ 4.6 / 5.0 112 Verified Reviews		<b>Vehicle serviced</b> Tires rotated Oil and filter changed
04/03/2014	Michigan Motor Vehicle Dept. Brooklyn, MI		<b>Registration issued or renewed</b>
09/22/2014 10,942	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Tires rotated

[^ Back To Top](#)

02/27/2015	17,705	Englewood Ford Englewood, FL 941-475-5444 englewood-ford.net ★ 4.9 / 5.0 662 Verified Reviews ❤️ 869 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Tires rotated Brakes checked Battery/charging system checked Tire condition and pressure checked
04/07/2015		Michigan Motor Vehicle Dept. Brooklyn, MI		<b>Registration issued or renewed</b>
10/07/2015	23,649	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Maintenance reminder reset Alignment checked Four wheel alignment performed Oil and filter changed Tires rotated Alignment performed
11/11/2015	24,261	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle serviced</b> Front wheel bearing(s)/hub(s) replaced
03/04/2016	29,928	Englewood Ford Englewood, FL 941-475-5444 englewood-ford.net ★ 4.9 / 5.0 662 Verified Reviews ❤️ 869 Customer Favorites		<b>Vehicle serviced</b> Maintenance inspection completed Battery/charging system checked Oil and filter changed Tire condition and pressure checked Brakes checked
03/30/2016		Michigan Motor Vehicle Dept. Brooklyn, MI		<b>Registration issued or renewed</b>
04/08/2016	32,505	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews		<b>Vehicle offered for sale</b>

[^ Back To Top](#)

04/08/2016  
 Guthrie Ford  
 Brooklyn, MI  
 517-592-2112  
 guthrieford.com  
 ★ 4.8 / 5.0  
 13 Verified Reviews





**Vehicle serviced**  
 Pre-delivery inspection completed  
 Wiper(s) replaced  
 Oil and filter changed


Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

01/26/2017  
 Ford Blue Advantage  
 Certified Dealer  
 Brooklyn, MI

**Sold as a Ford Blue Advantage certified used vehicle**





 **Owner 2**  
 Purchased: 2017



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
 12,786 mi/yr

Date	Mileage	Source	Comments
01/31/2017	34,685	Michigan Motor Vehicle Dept. Jackson, MI Title #220F0300538	<b>Title issued or updated</b> New owner reported
04/07/2017	35,428	Guthrie Ford Brooklyn, MI 517-592-2112 guthrieford.com ★ 4.8 / 5.0 13 Verified Reviews	 <b>Vehicle serviced</b> Maintenance inspection completed Brakes checked Tires rotated Fluids checked Maintenance reminder reset
12/13/2018	48,624	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https://visiontireandauto.com/ ★ 4.8 / 5.0 57 Verified Reviews ♥ 551 Customer Favorites	 <b>Vehicle serviced</b> Battery/charging system checked

^ Back To Top

01/30/2019 49,943

Vision Tire & Auto -  
Jackson  
Jackson, MI  
517-318-2585  
https://  
visiontireandauto.com/

★ 4.8 / 5.0

57 Verified Reviews

♥ 551 Customer Favorites



**Vehicle serviced**

Maintenance inspection completed  
Oil and filter changed  
Transmission fluid changed  
Antifreeze/coolant checked  
Cooling system serviced

05/20/2019

Damage Report





**Damage reported: minor damage**

Damage to front



**CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION**



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

06/20/2019 54,906

Vision Tire & Auto -  
Jackson  
Jackson, MI  
517-318-2585  
https://  
visiontireandauto.com/

★ 4.8 / 5.0

57 Verified Reviews






♥ 551 Customer Favorites



**Vehicle serviced**






Oil and filter changed

^ Back To Top
















09/04/2019	57,644	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/ ★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Upper control arm bushings replaced Four wheel alignment performed Headlight(s) replaced Air filter replaced Rear brake rotor(s) replaced Rear brake pads replaced Cabin air filter replaced/cleaned
09/16/2019	58,099	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/ ★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		<b>Vehicle serviced</b> Wheel bearing(s)/hub(s) replaced Rear wheel bearing(s)/hub(s) replaced
10/10/2019	59,014	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/ ★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		<b>Vehicle serviced</b> Headlight(s) replaced
12/24/2019	61,427	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/ ★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed Upper control arm bushings replaced Upper control arm(s) replaced Four wheel alignment performed
02/28/2020	63,369	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/ ★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		<b>Vehicle serviced</b> Blower motor replaced/repaired Blower motor serviced Battery/charging system checked


^ Back To Top





03/31/2020 64,514	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Tires rotated
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			
08/12/2020 70,319	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b>
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			
09/03/2020 71,244	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			
12/15/2020 75,054	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b> Oil and filter changed Control arm bushing(s) replaced Intake manifold gasket(s) replaced Four wheel alignment performed Antifreeze/coolant flushed/changed Transmission fluid flushed
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			
04/01/2021 81,108	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b> Oil and filter changed Tires rotated
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			

^ Back To Top

06/10/2021	85,240	<p>Vision Tire &amp; Auto - Jackson                  Jackson, MI                  517-318-2585  <a href="https://visiontireandauto.com/">https://visiontireandauto.com/</a>   <b>4.8 / 5.0</b>                  57 Verified Reviews   <b>551</b> Customer Favorites</p>	 <b>Vehicle serviced</b> Headlight(s) replaced Lights checked
06/28/2021	86,139	<p>Vision Tire &amp; Auto - Jackson                  Jackson, MI                  517-318-2585  <a href="https://visiontireandauto.com/">https://visiontireandauto.com/</a>   <b>4.8 / 5.0</b>                  57 Verified Reviews   <b>551</b> Customer Favorites</p>	 <b>Vehicle serviced</b>
07/15/2021	86,951	<p>Vision Tire &amp; Auto - Jackson                  Jackson, MI                  517-318-2585  <a href="https://visiontireandauto.com/">https://visiontireandauto.com/</a>   <b>4.8 / 5.0</b>                  57 Verified Reviews   <b>551</b> Customer Favorites</p>	 <b>Vehicle serviced</b> Battery/charging system checked
08/03/2021	87,965	<p>Vision Tire &amp; Auto - Jackson                  Jackson, MI                  517-318-2585  <a href="https://visiontireandauto.com/">https://visiontireandauto.com/</a>   <b>4.8 / 5.0</b>                  57 Verified Reviews   <b>551</b> Customer Favorites</p>	 <b>Vehicle serviced</b> Oil and filter changed
09/23/2021	90,844	<p>Vision Tire &amp; Auto - Jackson                  Jackson, MI                  517-318-2585  <a href="https://visiontireandauto.com/">https://visiontireandauto.com/</a>   <b>4.8 / 5.0</b>                  57 Verified Reviews   <b>551</b> Customer Favorites</p>	 <b>Vehicle serviced</b> Oil and filter changed

 [Back To Top](#)

10/12/2021 91,655	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b>
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites			
02/17/2022 96,928	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b>
★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		Sway bar bushing(s) replaced Wiper(s) replaced Headlight(s) replaced Sway bar link(s) replaced Front brake rotor(s) replaced Front brake pads replaced Control arm(s) replaced Oil and filter changed Rear wiper blade replaced Front wiper blades/refills replaced Brake rotor(s) replaced Four wheel alignment performed Tires rotated	
02/23/2022	Ford Motor Company	<b>Manufacturer Safety recall issued</b> NHTSA #20V675 Recall #20S62 REAR TOE LINK BALL JOINT INSPECTION Status: Remedy Available	
		Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information	
		⊖ <b>Learn more about this recall</b>	
<p><b>Description:</b> OUR RECORDS INDICATE THAT A FORD SAFETY RECALL WAS PREVIOUSLY PERFORMED ON YOUR VEHICLE TO REPLACE THE REAR SUSPENSION TOE LINKS. ASSESSMENT OF FIELD DATA INDICATES THAT THE BALL JOINT USED TO ATTACH THE REAR TOE LINK MAY BE SUSCEPTIBLE TO SEIZING IN CERTAIN HIGH CORROSION AREAS. A SEIZED TOE LINK BALL JOINT CAN INCREASE BENDING STRESSES IN THE TOE LINK AND POTENTIALLY LEAD TO A FRACTURE.</p> <p>REAR TOE LINK FRACTURE WHILE DRIVING COULD RESULT IN UNUSUAL VEHICLE HANDLING CHARACTERISTICS, OR DIFFICULTY CONTROLLING THE VEHICLE AND MAY INCREASE THE RISK OF A CRASH.</p> <p><b>Remedy:</b> FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH REAR TOE LINK BALL JOINTS AND, IF NECESSARY, REPLACE THE REAR WHEEL KNUCKLE(S), AND ADJUST REAR TOE FREE OF CHARGE (PARTS AND LABOR).</p>			

^ **Back To Top**

02/23/2022

Ford Motor Company

**Manufacturer Safety recall issued**

NHTSA #21V537  
 Recall #21S32 REAR TOE LINK  
 REPLACEMENT  
 Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

 **Learn more about this recall**


**Description:** VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS COULD EXPERIENCE A SEIZED REAR SUSPENSION TOE LINK BALL JOINT RESULTING IN A FRACTURED REAR SUSPENSION TOE LINK.

A REAR TOE LINK FRACTURE MAY CAUSE A LOSS OF STEERING CONTROL, INCREASING THE RISK OF A CRASH.

**Remedy:** FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE BOTH REAR TOE LINKS AND ADJUST REAR TOE FREE OF CHARGE PARTS AND LABOR.

06/30/2022 103,009

Vision Tire & Auto -  
 Jackson  
 Jackson, MI  
 517-318-2585  
[https://  
 visiontireandauto.com/](https://visiontireandauto.com/)

★ **4.8 / 5.0**  
 57 Verified Reviews  
 **551** Customer Favorites




**Vehicle serviced**

Serpentine belt replaced  
 Front wheel bearing(s)/hub(s)  
 replaced  
 Control arm(s) replaced  
 Rear brake rotor(s) replaced  
 Rear brake pads replaced  
 Oil and filter changed  
 Brake fluid flushed/changed  
 Four wheel alignment performed  
 Brakes checked

07/14/2022 103,190

Vision Tire & Auto -  
 Jackson  
 Jackson, MI  
 517-318-2585  
[https://  
 visiontireandauto.com/](https://visiontireandauto.com/)






★ **4.8 / 5.0**  
 57 Verified Reviews  
 **551** Customer Favorites



**Vehicle serviced**

Sway bar link(s) replaced

 **Back To Top**

01/16/2023	110,736	Vision Tire & Auto - Jackson Jackson, MI 517-318-2585 https:// visiontireandauto.com/		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed Starter replaced Battery/charging system checked
		★ <b>4.8 / 5.0</b> 57 Verified Reviews ❤️ <b>551</b> Customer Favorites		
05/09/2023	115,867	Mobile Medic Automotive Solutions & Repair Jackson, MI 517-962-5555		<b>Vehicle serviced</b> Oil and filter changed Wheel bearing(s)/hub(s) replaced Engine oil/fluid leak checked Sway bar link(s) replaced Starter replaced Tires rotated Steering/suspension checked
		★ <b>5.0 / 5.0</b> 8 Verified Reviews ❤️ <b>137</b> Customer Favorites		
05/30/2023	116,664	Mobile Medic Automotive Solutions & Repair Jackson, MI 517-962-5555		<b>Vehicle serviced</b> Thermostat replaced Lower radiator hose replaced Upper radiator hose replaced Radiator replaced
		★ <b>5.0 / 5.0</b> 8 Verified Reviews ❤️ <b>137</b> Customer Favorites		
08/23/2023	120,468	Mobile Medic Automotive Solutions & Repair Jackson, MI 517-962-5555		<b>Vehicle serviced</b> Oil and filter changed Tires rotated
		★ <b>5.0 / 5.0</b> 8 Verified Reviews ❤️ <b>137</b> Customer Favorites		
12/22/2023	Damage Report			<b>Accident reported: minor damage</b> It hit a deer It hit an animal Damage to right front

^ Back To Top



04/25/2024 127,204 Mobile Medic  
Automotive Solutions &  
Repair  
Jackson, MI  
517-962-5555



**Vehicle serviced**  
Oil and filter changed  
Tires rotated

★ 5.0 / 5.0

8 Verified Reviews

♥ 137 Customer Favorites

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/10/24 at 9:34:48 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/10/24 at 9:34:48 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Severity

Damage events result in one of the following severity levels:

- **Minor:** Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- **Moderate:** Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- **Severe:** Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Ford or Lincoln Mercury Recall

[^ Back To Top](#)

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

**Manufacturer Recall**

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

**New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
9/10/24 9:34:48 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 FORD EXPLORER vehicle (VIN: 1FM5K7D83EGA22058), which is based on information supplied to CARFAX and available as of 9/10/24 at 10:34 AM (EDT).**

Customer Signature

Date

Dealer Signature

Date

^ Back To Top