




### History-Based Value Report

#### History events affecting this vehicle's value



**\$9,010 Retail Value**



### Vehicle History Report™

US \$44.99

#### 2014 NISSAN MURANO SL

VIN: JN8AZ1MW1EW531084  
 4 DOOR WAGON/SPORT UTILITY  
 3.5L V6 F DOHC 24V GASOLINE  
 ALL WHEEL DRIVE  
 Original Window Sticker

No accidents or damage reported to CARFAX

**26** Service history records

CARFAX 1-Owner vehicle


Personal vehicle



Last owned in Michigan



**143,524** Last reported odometer reading

[^ Back To Top](#)

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/29/24 at 7:03:02 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Nissan dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2015
Type of owner	Personal
Estimated length of ownership	



[^ Back To Top](#)

Owned in the following states/provinces	Michigan
Estimated miles driven per year	20,495/yr
Last reported odometer reading	143,524






**CARFAX** Detailed History

 **Owner 1**  
Purchased: 2015







Personal Vehicle  
20,495 mi/yr

Date	Mileage	Source	Comments
08/04/2014		Nissan North America, Inc.	<p><b>Vehicle manufactured and shipped to original dealer</b></p>  <p>Original Window Sticker</p>
09/20/2014		<p>Fox Motor Group Grand Rapids, MI foxmotors.com</p> <p>★ 4.7 / 5.0 223 Verified Reviews ❤️ 882 Customer Favorites</p>	<b>Vehicle offered for sale</b>
09/20/2014	3	<p>Fox Nissan Grand Rapids, MI 616-942-8040 foxnissan.com</p> <p>★ 4.7 / 5.0 223 Verified Reviews ❤️ 882 Customer Favorites</p>	 <b>Vehicle serviced</b> Pre-delivery inspection completed Front license plate bracket installed/replaced
01/23/2015	455	<p>Fox Nissan Grand Rapids, MI 616-942-8040 foxnissan.com</p> <p>★ 4.7 / 5.0 223 Verified Reviews ❤️ 882 Customer Favorites</p>	<b>Vehicle sold</b>








[^ Back To Top](#)

01/23/2015		Michigan Motor Vehicle Dept. Posen, MI Title #603D0232103		<b>Title or registration issued</b> First owner reported Titled or registered as personal vehicle
02/27/2015	5,112	Larry H. Miller Nissan Mesa Mesa, AZ 866-766-1733 lhmnissanmesa.com		<b>Vehicle serviced</b> Maintenance inspection completed Oil and filter changed
06/29/2015	15,251	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ 4.4 / 5.0 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed
11/02/2015	22,651	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ 4.4 / 5.0 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed Front wiper blades/refills replaced Wiper(s) replaced
02/08/2016		Michigan Motor Vehicle Dept. Alpena, MI		<b>Registration issued or renewed</b> Registration updated when owner moved the vehicle to a new location
02/22/2016	29,864	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ 4.4 / 5.0 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed
07/26/2016	39,021	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ 4.4 / 5.0 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed






[^ Back To Top](#)

12/01/2016		Michigan Motor Vehicle Dept. Alpena, MI		<b>Registration issued or renewed</b>
12/07/2016	48,403	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ <b>4.4 / 5.0</b> 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed Tires rotated
04/12/2017	57,406	Walmart Auto Care Center Alpena, MI 989-354-0633 https:// www.walmart.com ★ <b>4.4 / 5.0</b> 17 Verified Reviews		<b>Vehicle serviced</b> Oil and filter changed Tires rotated Air filter checked
04/14/2017	57,690	Walmart Auto Care Center Belleville, MI 734-697-5508 https:// www.walmart.com ★ <b>4.8 / 5.0</b> 33 Verified Reviews		<b>Vehicle serviced</b>
09/05/2017	66,422	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ <b>4.8 / 5.0</b> 38 Verified Reviews ❤️ <b>26</b> Customer Favorites		<b>Vehicle serviced</b>
09/05/2017		Service Facility		<b>Vehicle serviced</b>
11/13/2017	70,708	Fox Ann Arbor Nissan Ann Arbor, MI 734-663-7770 foxannarbornissan.com/ ★ <b>4.6 / 5.0</b> 68 Verified Reviews		<b>Vehicle serviced</b> Maintenance inspection completed Tire condition and pressure checked Transmission checked

^ [Back To Top](#)

11/22/2017	71,088	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b>
11/22/2017		Service Facility		<b>Vehicle serviced</b>
02/03/2018	77,166	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
02/03/2018		Service Facility		<b>Vehicle serviced</b> Oil and filter changed
03/29/2018		Michigan Motor Vehicle Dept. Alpena, MI		<b>Registration issued or renewed</b> Registration updated when owner moved the vehicle to a new location
06/07/2018	84,335	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
06/07/2018		Service Facility		<b>Vehicle serviced</b> Oil and filter changed
11/28/2018	90,581	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Air filter replaced Oil and filter changed
04/09/2019		Michigan Motor Vehicle Dept. Ann Arbor, MI		<b>Registration issued or renewed</b> Registration updated when owner moved the vehicle to a new location

[^ Back To Top](#)

08/31/2019	97,586	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
03/06/2020	104,943	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed
03/06/2020		Michigan Motor Vehicle Dept. Ann Arbor, MI		<b>Registration issued or renewed</b>
05/28/2020	108,951	Hoover Street Auto Repair Ann Arbor, MI 734-913-6272 hooverstreetauto.com/ ★ 4.9 / 5.0 31 Verified Reviews ❤️ 31 Customer Favorites		<b>Vehicle serviced</b> Alignment checked Tire condition and pressure checked Steering/suspension checked Alignment performed Steering gear replaced Four wheel alignment performed Drivability/performance checked Steering wheel centered Power steering fluid flushed/changed
09/08/2020	116,776	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Air filter replaced Oil and filter changed
02/11/2021		Michigan Motor Vehicle Dept. Standish, MI		<b>Registration issued or renewed</b> Registration updated when owner moved the vehicle to a new location
02/22/2021	124,320	State Street Auto Wash & Lube Alpena, MI 989-356-2722 ★ 4.8 / 5.0 38 Verified Reviews ❤️ 26 Customer Favorites		<b>Vehicle serviced</b> Oil and filter changed

[^ Back To Top](#)

06/01/2021

Nissan North America Inc.

**Manufacturer Service Campaign issued**

Campaign #P0A08 MUR QST BRK  
FLD FLH NTB21047  
Status: Remedy Available

Locate an authorized Nissan dealer near you to obtain more information about this campaign

⊖ **Learn more about this campaign**

**Description:** A potential chemical reaction between the valve surface coating (Chromate layer) and the DOT3 brake fluid may cause a Gel to form around the normally closed ( NC ) valve. In some cases, it can cause the NC valve to be stuck open. The NC valve inside the ABS actuator may stick open and direct additional brake fluid flow to a reservoir inside the ABS actuator. As a result, the brake fluid pressure may fluctuate and the customer may experience increased brake pedal travel.

Customer may experience increased brake pedal travel (soft brake pedal) in the event of ABS activation. Normal braking is unaffected.

**Remedy:** All affected vehicles will have the brake fluid replaced (DOT3 to DOT4 fluid). Dealers will inspect the ABS actuator using Consult. If needed, the ABS actuator will be replaced. An owner s manual insert will be provided to customers with instruction to use DOT4 brake fluid to prevent the subject condition from reoccurring, and the brake fluid reservoir cap will be changed. This service, which is conducted at no charge to you for parts and labor, could take up to four and a half (4.5) hours to complete depending on the inspection results. However, your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule or if the ABS actuator requires replacement.

07/09/2021 130,863

State Street Auto Wash & Lube  
Alpena, MI  
989-356-2722



**Vehicle serviced**

Oil and filter changed

★ 4.8 / 5.0

38 Verified Reviews

♥ 26 Customer Favorites

01/22/2022 143,524

Up North Truck & Tire  
Alpena, MI  
989-340-0849  
https://upnorthtire.com/



**Vehicle serviced**

Four tires balanced  
Four tires mounted

02/07/2022

Michigan  
Motor Vehicle Dept.  
Alpena, MI

**Registration issued or renewed**

Registration updated when owner moved the vehicle to a new location



Hmm, we haven't received any information on this car since February 2022. Before you buy, ask the seller for recent service or repair records.

^ **Back To Top**



Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us:



[facebook.com/CARFAX](https://facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
6/29/24 7:03:02 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 NISSAN MURANO vehicle (VIN: JN8AZ1MW1EW531084), which is based on information supplied to CARFAX and available as of 6/29/24 at 8:03 AM (EDT).**

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date

[^ Back To Top](#)