



Report

US \$44.99

2004 Volkswagen Phaeton Premiere Edition W12

VIN: WVWAH63D048007844 |

Sedan 4 DR | 6.0L W12 F | Gasoline | All wheel drive

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



DAMAGE

Damage Reported

Potential Odometer Rollback Indicated

65 Service History Records

2 Previous Owners

Personal Vehicle

Last Owned in California

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/27/26 at 8:04:25 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

03/01/2008

Damage reported

Event 2

01/05/2015

Damage reported: minor damage


Damage Severity Scale



Minor

Moderate

Severe



Additional History

Not all accidents / issues are reported to CARFAX





Owner 1

Owner 2













Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check Potential odometer rollback indicated.	Potential Rollback	No New Issues Indicated
Accident / Damage Damage reported: 03/01/2008 and 01/05/2015.	Damage Reported	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired



CARFAX Title History	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem	No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	No Problem	No Problem

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2004	2015
Type of owner	Personal	Personal
Estimated length of ownership	10 yrs. 6 mo.	10 yrs. 10 mo.
Owned in the following states/provinces	California	California
Estimated miles driven per year	---	---
Last reported odometer reading	---	110,508














CARFAX Detailed History			
Owner 1 Purchased: 2004			Personal Vehicle
Date	Mileage	Source	Comments
Not Reported		NICB	Vehicle manufactured and shipped to original dealer
11/12/2003	3	Service Facility	 Vehicle serviced
11/12/2003		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com	 Vehicle serviced - Pre-delivery inspection completed
11/25/2003	20	Service Facility	 Vehicle serviced
11/25/2003		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com	 Vehicle serviced - Battery/charging system checked - Battery charged - Engine/powertrain computer/module checked









- Steering wheel replaced









01/16/2004	25	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
02/03/2004	29	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
03/16/2004	36	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Vehicle washed/detailed
04/02/2004		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
05/25/2004		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
08/31/2004		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
10/20/2004		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Battery/charging system checked - Battery replaced - Drivability/performance checked
11/04/2004	89	California Motor Vehicle Dept. Danville, CA		Title issued or updated - First owner reported - Titled or registered as personal vehicle - Loan or lien reported
11/15/2004	257	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Electrical system checked - GPS/Navigation module/computer replaced
11/25/2004		California Motor Vehicle Dept. San Ramon, CA		Title issued or updated - Loan or lien reported - Registration updated when owner moved the vehicle to a new location
12/30/2004	1,339	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Drivability/performance checked - Engine/powertrain computer/module checked - Headliner replaced
01/28/2005	4,365	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - 5,000 mile service performed - 8,000 kilometer service performed - Anti-theft/keyless device/alarm installed - Drivability/performance checked - Engine/powertrain computer/module checked - Fuel injector(s) replaced
02/22/2005	5,450	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Front door adjusted
03/24/2005	6,604	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Tire condition and pressure checked

06/07/2005	9,455	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - 10,000 mile service performed - Radiator replaced - Tire condition and pressure checked
06/30/2005	9,700	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Armrest replaced
08/09/2005	11,984	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Engine/powertrain computer/module checked
10/27/2005	15,652	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Battery/charging system checked - Battery replaced - Headliner replaced - Noise checked - Right sunvisor replaced
12/27/2005	16,903	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
02/15/2006	18,234	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
04/27/2006	19,834	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - 20,000 mile service performed - One tire mounted
11/30/2006	21,719	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
12/29/2006		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
01/31/2007	21,947	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
02/27/2007	22,136	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
08/29/2007		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
11/27/2007	22,185	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - 20,000 mile service performed
12/13/2007	22,895	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Battery/charging system checked - Injector driver module replaced
12/24/2007	23,255	Dublin Volkswagen Dublin, CA 925-829-0800		Vehicle serviced



vwofdublin.com


03/01/2008		Damage Report		Damage reported CARFAX recommends checking for damage during your pre-purchase inspection.
03/26/2008		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Battery/charging system checked - Battery replaced
04/09/2008		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
05/21/2008		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
01/20/2009	22,661	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Anti-theft/keyless remote battery replaced - Drivability/performance checked - Tire condition and pressure checked POTENTIAL ODOMETER ROLLBACK <div style="border: 1px solid blue; padding: 5px; margin-top: 5px;">There are signs of potential odometer rollback here, so verify the mileage with the seller. I know I would.</div>
05/01/2009	22,703	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Tire pressure sensor replaced
06/30/2009	22,874	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
07/16/2009	22,875	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Recommended maintenance performed
08/06/2009	22,938	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
08/19/2009	22,950	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
09/08/2009		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
11/24/2009		California Motor Vehicle Dept. San Ramon, CA		Title issued or updated - Loan or lien released
01/07/2010	23,132	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
08/24/2010		Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced

08/24/2010	24,038	California Inspection Station San Ramon, CA		Passed emissions inspection
02/18/2011	24,247	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
06/28/2011	28,248	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Tire condition and pressure checked - Tires rotated
09/16/2011		California Motor Vehicle Dept. Danville, CA		Registration updated when owner moved the vehicle to a new location
09/26/2011	32,448	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Tire condition and pressure checked - Wiper(s) replaced
11/14/2011	33,865	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced
12/28/2011	35,306	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Tire condition and pressure checked
05/10/2012	38,892	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked
06/01/2012	39,372	Dublin Volkswagen Dublin, CA 925-829-0800 vwofdublin.com		Vehicle serviced - Automatic transmission pan gasket replaced - Tire condition and pressure checked - Transmission fluid changed
05/03/2013	39,980	California Inspection Station San Ramon, CA		Passed emissions inspection
03/18/2014	41,084	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Engine/powertrain computer/module checked - Tire condition and pressure checked
04/07/2014	41,572	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites		Vehicle serviced - Engine/powertrain computer/module checked - Tire condition and pressure checked
07/10/2014	43,570	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Brakes checked - Front brake pads replaced - Oil and filter changed - Steering/suspension checked - Tire condition and pressure checked
09/12/2014	46,322	California Inspection Station		Passed emissions inspection


11/05/2014	48,542	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Engine/powertrain computer/module checked - Tire condition and pressure checked
<div data-bbox="94 625 462 730" style="float: left; width: 25%;"> <p>CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION</p> </div> <div data-bbox="110 289 240 315" style="float: left; width: 20%;">01/05/2015</div> <div data-bbox="467 289 633 315" style="float: left; width: 25%;">Damage Report</div> <div data-bbox="925 289 1279 346" style="float: right; width: 30%;"> Damage reported: minor damage - Damage to front </div> <div data-bbox="852 378 1258 535" style="margin: 10px auto; width: 80%;"> <p style="text-align: center;">Damage Severity Scale</p>  <p style="text-align: center;">Minor Moderate Severe</p> </div> <div data-bbox="852 546 1258 987" style="margin: 10px auto; width: 80%;"> <p style="text-align: center;">Damage Location</p>  <p style="text-align: center;">FRONT</p> <p style="text-align: center;">LEFT RIGHT</p> <p style="text-align: center;">REAR</p> </div>			
01/31/2015		Big O Tires #005073 Danville, CA 925-831-8331 bigotire.com ★ 4.6 / 5.0 142 Verified Reviews ♥ 93 Customer Favorites	 Vehicle serviced
02/02/2015	51,844	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - 50,000 mile service performed - Battery/charging system checked - Drivability/performance checked - Tire condition and pressure checked - Tires rotated - Transmission replaced
03/06/2015	52,770	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites	 Vehicle serviced - Electrical system checked - Lock cylinders checked - Radio replaced - Shift lever/assembly replaced - Tire condition and pressure checked
03/20/2015		Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews ♥ 4,646 Customer Favorites	 Vehicle serviced - Tire condition and pressure checked
04/01/2015	53,221	Dublin Volkswagen Dublin, CA 925-829-0800 dublinvolkswagen.com/ ★ 4.4 / 5.0 116 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Electrical system checked - Steering/suspension checked - Tire condition and pressure checked

♥ 4,646 Customer Favorites

05/15/2015		Volkswagen of Oakland Oakland, CA 510-834-7711 vwfoakland.com ★ 4.4 / 5.0 69 Verified Reviews		Vehicle offered for sale
05/15/2015	54,347	California Inspection Station		Passed emissions inspection
05/22/2015	54,350	Volkswagen of Oakland Oakland, CA 510-281-8909 vwfoakland.com ★ 4.7 / 5.0 83 Verified Reviews ♥ 114 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed - Four tires balanced - Four tires mounted - Emissions inspection performed - Tire(s) replaced
05/22/2015		California Motor Vehicle Dept. Alamo, CA		Registration updated when owner moved the vehicle to a new location
05/31/2015		Volkswagen of Oakland Oakland, CA 510-834-7711 vwfoakland.com ★ 4.4 / 5.0 69 Verified Reviews		Vehicle sold
06/03/2015		Dealer Inventory		Vehicle offered for sale
06/05/2015	54,360	Volkswagen of Oakland Oakland, CA 510-281-8909 vwfoakland.com ★ 4.7 / 5.0 83 Verified Reviews ♥ 114 Customer Favorites		Vehicle serviced - Cooling system checked

 **Owner 2**
Purchased: 2015

Personal Vehicle

Date	Mileage	Source		Comments
06/07/2015	54,536	California Motor Vehicle Dept. Huntington Beach, CA		Odometer reading reported
06/26/2015		California Motor Vehicle Dept. Huntington Beach, CA		Title issued or updated - New owner reported - Loan or lien reported
09/10/2015		California Motor Vehicle Dept. Huntington Beach, CA		Registration updated when owner moved the vehicle to a new location
10/11/2016	65,753	California Inspection Station		Passed emissions inspection
10/10/2018	80,769	California Inspection Station		Passed emissions inspection
04/26/2019		California Motor Vehicle Dept. Huntington Beach, CA		Title issued or updated - Loan or lien released
08/21/2020	94,691	California Inspection Station		Failed emissions inspection
10/07/2020	94,836	Trinity European Service & Repair Huntington Beach, CA 714-841-0117 ★ 5.0 / 5.0 126 Verified Reviews		Vehicle serviced - Emissions inspection performed - Serpentine belt replaced

♥ 45 Customer Favorites

10/26/2020	95,423	California Inspection Station		Passed emissions inspection
12/08/2020	95,501	Trinity European Service & Repair Huntington Beach, CA 714-841-0117 ★ 5.0 / 5.0 126 Verified Reviews ♥ 45 Customer Favorites	🔧	Vehicle serviced
12/13/2021	100,788	Trinity European Service & Repair Huntington Beach, CA 714-841-0117 ★ 5.0 / 5.0 126 Verified Reviews ♥ 45 Customer Favorites	🔧	Vehicle serviced - Transmission fluid changed
08/26/2022	103,250	California Inspection Station		Passed emissions inspection
03/01/2023	105,633	Trinity European Service & Repair Huntington Beach, CA 714-841-0117 ★ 5.0 / 5.0 126 Verified Reviews ♥ 45 Customer Favorites	🔧	Vehicle serviced - Fluids checked - Transmission checked - Transmission fluid changed
10/09/2024	110,508	California Inspection Station		Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/27/26 at 8:04:25 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Odometer Rollback

If a more recent odometer reading is less than an older reading, then the odometer may have been tampered with and "rolled back." CARFAX analyzes the mileage history and the sources of this information to indicate a potential odometer rollback.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
4/27/26 8:04:25 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2004 VOLKSWAGEN PHAETON vehicle (VIN: WVWAH63D048007844), which is based on information supplied to CARFAX and available as of 4/27/26 at 9:04 AM (EDT).

Customer Signature

Date

Dealer Signature

Date